

Location Information			Fortan Aread Berlin				Customer-Owned Portion			Other Potential Sources of Lead Lead Service Line Replaceme			e Replacement	
Unique Service Line ID	Location Ide Street Address	ntiller (required) Other Location Identifier	System-Owned Partion Service Line Material Classification (required)	If Non-Lead in Column D, Was Material Ever Previously Lead?	Basis of Material Classification (required)	Notes	Customer-Owned Portion Service Line Material Classification (required)	Bask of Material Classification (required)	Notes	Entire Service Line Material Classification (required)	is there a Lead Connector?	is there Lead Solder in the Service Line?	(LS) Date of System- owned LSLR	UR) Date of Customer owned LSLR
A Unique ID is recommended for each service line.	Noter systems must basit a solarmatineerising (for o theo location sites(for, of 12, paratrianster, instan- detablic specifi	aldersarsef af arveise breast theo pitem daes not are addresses for ter optime could include a subger et, internetion, dooi, or ather parvaire for incutions.	Dropdown list includes recommended subclossifications. if "Non-Lead Other", deucribe in Notes field	Dropdown list. Select Yes, No, or Don't know. Important for determining if downstraam/customer- awned golvanized service line requires replacement	Select option from drop down list. (f "Other," describe in the Notes field	Use this field for documenting additional inferent information.	Dropdown list includes recommended subclossifications. If non- iead other, describe in Notes field.	Select option from drap down list.	Use this field for documenting additional relevant information.	Select the proper classification using dropdown list and "Classifying SLs" tab.	For example, lead gooseneck or pigtal where the water main is connected to the service line	Select Yes, No, or Don't Know		
7002	19820, 157 57 CT E, LANE TANPS, WA S8231-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water system through maintenans, repairs ar replacement since the Datatic took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system	Linknown - Unlikely Irod	Other	No Lead has ever been detected or discovered in any partian of the water synchro through maintennor, repains ar replaament since the District took over operations of this system. No Lead has ever been detected or discovered in any position of the water summ	Usknown				
857003	20018, 1ST ST CT E, LAKE TAPPS, WA SE201-		Unknown - Unlikely lead	Don't know	Other	No.Lead has ever been detected or discovered in any partion of the water system through maintenanov, repairs or replacement since the District took over operations of this statem. No.Lead has ever been	Linknown - Linikely Irad	Other	No Lead has ever been detected or discovered in any partian of the water system through maintenance, repairs or replacement since the District took over operations of this system.	Unknown				
857004	22, 199 AVE CT E, LAKE TAPPS, WA SE251-		Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs	Non-lead - Other	Installation date after lead	of this system.	Usknown				
007005	21, 199 AVE CT E, LARE TAUPS, WA, SE221-		Unknown - Unlikely lead	Don't know	Other	or ingluedinger lane tete arbitration to experisions arbitrations and the server been detected or discovered in any bearing of the water spaces the application of the water spaces are applied on the server been distribution of the server been distribution of the server been approximate the server been approxi	Non-lead - Other	Installation date after lead box		Usknown				
007006	20, 199 AVE CT E, LAKE TAPPS, WA, SR281-		Non-lead - Plastic	Don't know	Service line repair or replacement record	Service line repair/replacement done	Non-lead - Other	Installation date after lead ban		Non-Lead				
887807	22, 190 AVE CT E, LAKE TAPPS, WA, SE201-		Unknown - Unlikely lead	Don't know	Other	or replacement since the District took over operations	Linknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any parties of the water system through maintenance, repairs or replacement since the District took over openations with system	Unknown				
007008	118, 198 AVE 6, LAKE TARPS, WA, 98291-		Unknown - Unlikely lead	Don't know	Other	Artikis sustam No Lead has ever been detected or discovered in any parties of the water system through mainteenanor, repairs or replacement since the Datist took over operations of this sustem. No Lead has ever been	Linknown - Unlikely lead	Other	of this sources No Lead has even been detected or discovered in any partials of the water system through realistenance, repairs or replacement since the District took over openations of this seaters. No Lead has even been	Usknown				
007009	122, 188 AVE E, LAKE TARPS, WA, 88291-		Linknown - Unlikely lead	Don't know	Other	portion of the water system through maintenance, repairs or replacement since the	Linknown - Unlikely lead	Other	artected of discovered in any partian of the water system through maintenance, repairs or replacement since the	Unknown				
007010	212, 288 AVE E, LAKE TARPS, WA, 88293-		Linknown - Unlikely lead	Don't know	Other	District took over operations of this variant No Lead has ever been detected or discovered in any portion of the water system through maintenana, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any	Linknown - Unlikely lead	Other	District took over operations of this numbers No Lead has ever been detected or discovered in com- partion of the water synetre through realitenance, repairs or replacement since the District took over operations of this seaters.	Unknown				
007014	20115, 2 5T E, LANE TAPPS, WA, SE221-		Unknown - Unlikely lead	Don't know	Other	portion of the water system through maintenance, repairs or replacement since the	Non-lead - Other	Installation date after lead ban	of this neaters.	Usknown				
007016	20014, 2 ST E, LANE TAPPS, WA, SE221-		Unknown - Unlikely lead	Don't know	Other	of this reatern. No Lead has ever been detected or discovered in any portion of the water speaks through maintenance, repairs or replacement since the	Non-lead - Other	Installation date after lead ban		Usknown				
667017	20120, 2 ST E, LANE TARPS, WA, SE221-		Unknown - Unlikely lead	Don't know	Other	Other tools over operations of this system. No Lead has ever been detected or discovered in any partian of the water system through maintenanor, repairs or replacement since the Datatic tools over operations of this system.	Linknown - Unlikely Irod	Other	No Lead has ever been detected or discovered in any partias of the water system through maintenance, repains or replacement since the District took over operations of this system.	Usknown				
007018	303, 202 AVE E, LAKE TARPS, WA, 88201-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any partian of the water system	Linknown - Linikely lead	Other	No Lead has ever been detected or discovered in any partian of the water sysetm	Usknown				
007019	20208, 2 5T 5, LAKE TARPS, WA, SE201-		Linknown - Unlikely lead	Don't know	Other	though maintenanar, repairs or replacement since the Datatic took over operations of this restorm. No Load hose over been detected or discovered in any portion of the water system though maintenanar, repairs or replacement since the Datatic took over operations of this restorm.	Linknown - Unlikely lead	Other	through maintenance, repains an replacement since the Dismit took over openations of this system. No Lead has ever been detected or allowered in con- partion of the water system through maintenance, repains an replacement since the Dismit took over openations of this system.	Usknown				
657020	20410, 2 ST E, LAKE TARPS, WA, 88291-		Linknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any partian of the water sysetm	Linknown - Unlikely Irod	Other	of this system. No Lead has ever been detected or discovered in any parties of the water system through maintenance, repairs a replacement since the District took over operations of this system.	Usknown				
007022	215, 205 АНТ Б, LAKE ТАКРБ, ША, 98291-		Unknown - Unlikely lead	Don't know	Other	trinugin mantenana, regars ar replacement since the Datisti took over operations of this statem. No Lead has ever been detected or discovered in any portion of the water system through maintenanar, regains ar replacement since the Datist took over operations of this statem. No Lead has ever been	Non-lead - Other	Installation date after lead ban		Usknown				
807023	222, 205 AVE E, LAKE TAPPS, WA, SE201-		Linknown - Linikely lead	Don't know	Other	detected or discovered in any portion of the water system through molitenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead dan		Usknown				
007024	219, 205 AVE E, LAKE TARPS, WA, SE291-		Unknown - Unlikely lead	Don't know	Other	detected or discovered in any portion of the water system through maintenanae, repairs or replacement since the District took over operations of this system. No Lead has ever been	Non-lead - Other	Installation date after lead box	No Lead has ever been	Unknown				
00702S	217, 205 AVE E, LAKE TARPS, WA, 88201-		Unknown - Unlikely lead	Don't know	Other	detected or discovered is any parties of the water system through mailtenana, repairs through mailtenana, repairs of this system. No Lead has ever operations of this system. No Lead has ever been detected or discovered is any parties of the water system through mailtenanar, repairs through mailtenanar, repairs through mailtenanar, repairs through mailtenanar, repairs	Linknown - Linikely lead	Other	detected or discovered in any partian of the water sysetm through maintenance, repairs or replacement since the	Unknown				
007028	110, 205 AVE E, LAKE TARPS, WA, BE201-		Unknown - Unlikely lead	Don't know	Other	detected or discovered in any portion of the water sysetm through maletenance, repairs or replacement since the District took over operations of this system. No Lead has ever been	Linknown - Unlikely lead	Other	District tool over operations of this sustem. No Lead has every been detected or discovered in any parties of the water system through evalutemana, repairs or replacement since the District took over operations of this system.	Usknown				
007029	216, 205 AVE E, LAKE TAPPS, WA, 98201-		Linknown - Liniikely lead	Don't know	Other	of this restern. No Lead has ever been detected or discovered in any partian of the water system through maintenanar, repairs or replacement since the District took over operations of this system. No Lead has ever been	Non-lead - Other	Installation date after lead bon	No Lead has ever been	Usknown				
007030	222, 205 AVE 5, LAKE TARPS, WA, SE201-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. Service line material is poly	Linknown - Unlikely Irod	Other	No Lead has ever been detected or discovered in any partion of the water sysetim through realistenance, repairs ar replacement since the District took over operations of this system.	Usknown				
007031	20409, 2 ST E, LAKE TAPPS, WA, 98291-		Non-lead - Other	Don't know	Other	Service line reinstalled an 06/16/2000 No Lead has ever been	Non-lead - Other	Installation date after lead ban	No Lead has ever been	Non-Lead				
887032	20307, 3 ST E, LANE TARPS, WA, SE231-		Unknown - Unlikely lead	Don't know	Other	portion of the water spectra through molecures, registry or replacement since the Detrist took over operations of this statem. Bervice line minimalian poly- Service line minimalian differential of disease with the differential of disease with the differential of disease with the mass main and the state spectra of this materia. A fability of the water spectra of this material	Linknown - Unlikely lead	Other	detected or discovered in any partian of the water sysetm through maletenance, repairs or replacement since the	Unknown				
007023	20215, 3 5T E, LANE TARPS, WA, SE201-		Unknown - Unlikely lead	Don't know	Other	Antice tools over operations or this reacham No Lead has ever been detected or discovered in any pottion of the water system through maintenance, repairs or replacement since the District took over operations of this system. Service line material is poly	Linknown - Unlikely lead	Other	Interest too over operations of this nations No Lead has every been detected or discovered in any parties of the water system through realitenance, repairs or replacement since the District took over operations of this sectors.	Unknown				
007034	20121, 3 ST E, LARE TARPS, WA, SE221- 20015, 3 ST E, LARE TARPS, WA, SE221-		Non-lead - Other Unknown - Unlikely lead	Don't know	Service line repair or replacement record Other	Datist cast over operations of this statem. Service line material is paly Repair/opipacement done 02/20/2020 No.Lead has ever been detected or discovered in any partian of the water system through mainteenane, repairs or replacement since the Datist cast were operations	Non-lead - Other Linknown - Unlikely lead	Anatolistion date after lead bon Other	No Lead has ever been detected or discovered in any partian of the water system through maintenance, repairs or replacement since the District took over operations	Non-Lead Lisknown				
007036	20012, 2 ST E, LAKE TARPS, WA, 38221-		Unknown - Unlikely lead	Don't know	Other	District task over operations of this restance Mail and has ever been detected or discovered in any partion of the water system through mailcenson, regalar or replacement since the District task over operations of this restem. No.Lead has ever been detected or discovered in any	Non-lead - Other	Installation date after lead	District took over operations of this sustain	Unknown				
667037	208, 205 AVE E, LAKE TARPS, WA, SB221-		Unknown - Unlikely lead	Don't know	Other	portion of the water system through maintenance, repairs or replacement since the	Non-lead - Other	Installation date after lead		Unknown				
007038	206, 205 AVE E, LAKE TARPS. WA SE221-		Non-lead - Other	No	installation record	of this system. Service line material is poly	Non-lead - Other	Installation date after lead box		Non-Lead				
007039	74495, WA 38231- 118, 198 AVE E (42), LAKE TAPPS, WA S8231-		Unknown - Unlikely lead	Don't know	Other	of this rate over operations of this statem. Service like restrict it poly installation deter wor in 1999 No Lead has ever been detected or discovered in any partian of the water system through mainteenanar, regains or replacement since the Dataset taak over operations	Linknown - Unlikely Irad	Other	No Lead has ever been detected or discovered in any partian of the water system through maintenance, repairs or replacement since the District took over operations of the system.	Usknown				
887040	207, 199 AVE CT E, LAKE TAPPS, WA SR221-		Unknown - Unlikely lead	Don't know	Other	portion of the water system through multicenson, repairs ar replacement since the Obtaint took over operations will be a set of the detected of discovered is any partial of the water system through multicenson, repairs ar replacement since the Statisti took over operations of this sector. Statist cook over operations district new installed MCH/CONE	Linknown - Unlikely lead	Other	partian of the water system though maintenance, repair or replaammet since the District taok were openations Alo Lead has ever heren detected or discovered in acy partian of the water system though maintenance, repair though maintenance, repair or replaammet since the District taok were openations of this system.	Usinown				
007041	19818, 1 ST CT E, LAKE TAPPS, WA, GROOF.		Non-lead - Other	No	Installation record	Service line material is poly Service line installed ACTIL/2015	Non-lead - Other	Installation date after lead ban		Non-Lead				