Detailed Inventory

PWS Name: Valley Water System

PWSID: 01250

Date Last Updated:

Purpose of this worksheet: This is a modified version of EPA's template; modified to assist water systems with completing the minimum data elements needed for a lead service line inventory.

General Instructions: Each row in this worksheet represents one service line connecting the water main to the customer's plumbing. The worksheet includes required and recommended elements; the columns with the aqua shading and listed required need to be completed to meet the requirements of the LCRR. Important notes for each column are in Row 12. Note that users can freeze panes to enable them to see the headings and notes when entering data. The worksheet is formatted for approximately 5,000 entries.

	Location Information		System-Own	ed Portion			Customer-Owned Portic	on		Other Potential So	urces of Lead	Lead Service Lin	ne Replacement LR)
Unique Service Line ID	Location Identifier (required) Street Address Other Location Identifier	System-Owned Portion Service Line Material Classification (required)	If Non-Lead in Column D, Was Material Ever Previously Lead?	Basis of Material Classification (required)	Notes	Customer-Owned Portion Service Line Material Classification (required)	Basis of Material Classification (required)	Notes	Entire Service Line Material Classification (required)	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Date of System- owned LSLR	Date of Customer- owned LSLR
A Unique ID is recommended for each service line.	Water systems must track addresses of all service lines in their internal inventory. If the system does not use addresses for their location identifier, other options could include a unique ID, parcel number, landmark, intersection, block, or other details to specify service line locations.	Dropdown list includes recommended subclassifications. If "Non-Lead Other", describe in Notes field	Dropdown list. Select Yes, No, or Don't know. Important for determining if downstream/ customer- owned galvanized service line requires replacement	Select option from drop down list. If "Other," describe in the Notes field	Use this field for documenting additional relevant information.	Dropdown list includes recommended subclassifications. If non-lead other, describe in Notes field.	Select option from drop down list.	Use this field for documenting additional relevant information.	Select the proper classification using dropdown list and "Classifying SLs" tab.	For example, lead gooseneck or pigtail where the water main is connected to the service line	Select Yes, No, or Don't Know		
000001	14307, 128 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown				
000002	14221, 128 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown				
000003	14127, 128 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown				
000005	7904, 143 AVE CT E, PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown				
000007	8401, SR 162 E, PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown				

					No Lead has ever been			No Lead has ever been			
					detected or discovered in any portion of the water sysetm			detected or discovered in any portion of the water sysetm			
000010	14206, 128 ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98374-	,			or replacement since the	,		or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000011	12920, SR 162 E,	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs	Unknown - Unlikely Lead	Other	portion of the water sysetm through maintenance, repairs	Hnknown		
000011	PUYALLUP, WA, 98374-	Onknown Chinkely lead	DOIT CKNOW	Other	or replacement since the	Olikilowii Olilikely Ledd	Other	or replacement since the	Olikilowii		
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000013	14220, 128 ST E,	Hakaana Halikah laad	Don't know	Othor	portion of the water sysetm	Unknown Unlikali Load	Othor	portion of the water sysetm	Unknown		
000012	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the	Unknown - Unlikely Lead	Other	through maintenance, repairs or replacement since the	Unknown		
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14509, 133 ST E,		- 111		portion of the water sysetm			portion of the water sysetm			
000013	ORTING, WA, 98360-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other		Unknown		
					or replacement since the District took over operations of			or replacement since the District took over operations			
					this system.			of this system.			
					No Lead has ever been			oj uno systemi			
					detected or discovered in any			Mobile home was 1981,			
	14411, 133 ST E,				portion of the water sysetm		Installation date after lead				
000014	ORTING, WA, 98360-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Non-lead - Other	ban	1999 when service was	Unknown		
					or replacement since the			installed			
					District took over operations of this system.						
					No Lead has ever been						
					detected or discovered in any						
	12216 145 AVE CT 5				portion of the water sysetm		Installation data after land				
000015	13216, 145 AVE CT E, ORTING, WA, 98360-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Non-lead - Other	Installation date after lead ban		Unknown		
	Christo, Wri, 30300				or replacement since the		Dun.				
					District took over operations of						
					this system. No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000016	13121, SR 162 E, ORTING, WA, 98360-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
	OKTING, WA, 98300-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system. No Lead has ever been			of this system. No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000017	13119, SR 162 E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
	ORTING, WA, 98360-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been detected or discovered in any			
					detected or discovered in any portion of the water sysetm			portion of the water sysetm			
000018	13015, SR 162 E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
	ORTING, WA, 98360-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
								No Lead has ever been			
					Constanting a second of the Constanting and the Constanting are second or the Constanting and the Constanting are second or th			detected or discovered in any			
000021	13009, SR 162 E,	Non-lead - Other	No	Installation record	Service line material is Poly Installation done on	Unknown - Unlikely Lead	Other	portion of the water sysetm through maintenance, repairs	Unknown		
000021	ORTING, WA, 98360-	Non-lead - Other	INU	mstallation record	01/24/2000	Onknown - Onnkery Lead	Other	or replacement since the	GHKHUWH		
					01/27/2000			District took over operations			
								of this system.			

					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000022	13005, SR 162 E,	Halmann Halikah laad	Don't know	Other	portion of the water sysetm	Halinawa Halikalı Laad	Other	portion of the water sysetm	Unknown		
000022	ORTING, WA, 98360-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the	Unknown - Unlikely Lead	Other	through maintenance, repairs or replacement since the	UNKNOWN		
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000023	12915, SR 162 E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
	ORTING, WA, 98360-				or replacement since the	,		or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	12903, SR 162 E,				portion of the water sysetm			portion of the water sysetm			
000024	ORTING, WA, 98360-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system. No Lead has ever been			of this system.			
					detected or discovered in any			No Lead has ever been detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000025	12815, SR 162 E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
	ORTING, WA, 98360-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14704, 128 ST E,				portion of the water sysetm			portion of the water sysetm			
000030	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
	7 0 77 12207 7 77 7 9 00 7 7				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000031	14812, 128 ST E,	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs	Unknown - Unlikely Lead	Other	portion of the water sysetm through maintenance, repairs	Unknown		
000031	PUYALLUP, WA, 98374-	Olikilowii - Olilikely ledd	Don't know	Other	or replacement since the	Olikilowii - Olilikely Ledd	Other	or replacement since the	Olikilowii		
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			, ,			
					detected or discovered in any						
	14C1C 120 CT F				portion of the water sysetm		Installation data after load				
000032	14616, 128 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Non-lead - Other	Installation date after lead ban		Unknown		
	FOTALLOF, WA, 98374-				or replacement since the		Duli				
					District took over operations of						
					this system.						
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000041	14828, 128 ST E,	Unknown Unlikabilisad	Don't know	Othor	portion of the water sysetm	Unknown Unlikely Lag-	Othor	portion of the water sysetm	Unknown		
000041	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the	Unknown - Unlikely Lead	Other	through maintenance, repairs or replacement since the	OHKHOWH		
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14000 120 CT 5				portion of the water sysetm			portion of the water sysetm			
000042	14908, 128 ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98374-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	15002, 128 ST E,				portion of the water sysetm			portion of the water sysetm			
000043	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			

000048	15006, 128 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000049	15004, 128 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000051	12725, 151 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000056	12529, 151 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000057	12512, 151 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000058	12511, 151 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000059	12503, 151 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000060	12421, 151 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000061	12416, 151 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000075	15003, 128 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		

					No Lead has ever been detected or discovered in any						
000076	14903, 128 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Mobile home was 1976, Quit Claim is 2006 when service was installed	Unknown		
000077	14619, 128 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000078	14611, 128 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000079	14601, 128 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000080	14521, 128 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000081	14515, 128 ST E, PUYALLUP, WA, 98374-	Non-lead - Other	Don't know	Service line repair/replacement record	Service line material is Poly Repair/Replacement done 06/30/2004	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000082	14505, 128 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000083	12627, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000084	14801, 128 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000090	12615, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		

March Marc						No Lead has ever been detected or discovered in any			No Lead has ever been detected or discovered in any			
April Apri	000091		Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm	Unknown - Unlikely Lead	Other	portion of the water sysetm	Hakaowa		
Company Comp	000031	PUYALLUP, WA, 98374-	onknown onlinely ledd	Bontanow	Guiei	or replacement since the	Omniowii Omniciy Ledd	ouic.	or replacement since the	Olimiowii		
Authority (Authority Company) Authority (Authority Company						this system.			of this system.			
						detected or discovered in any			detected or discovered in any			
Accordance of the control of the c	000092		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
Modern Market State Market Stat						District took over operations of			District took over operations			
DOUGH PARTER PORTER POR						No Lead has ever been			No Lead has ever been			
AND	000003	12223, SR 162 E,	the bores on the library level and	Danik karawa	Other	portion of the water sysetm	Habaria Hallish Land	Other	portion of the water sysetm	Halmanna.		
Company Comp	000093	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Otner	or replacement since the	Unknown - Unlikely Lead	Otner	or replacement since the	Unknown		
Appendix Marganes - (makey least 1/20 m)						this system.			· ·			
Description of the control of the co						detected or discovered in any						
## April 1997 ##	000094		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Non-lead - Other			Unknown		
2000 1200 1200 1200 1200 1200 1200 1200		, , , , , , , , , , , , , , , , , , , ,				District took over operations of						
And Cured the center from the company of the center of the						this system.						
And Cured the center from the company of the center of the		12107 SR 162 F										
detected or discovered in any portion of the water specific or discovered in any portion of the water specif	200094		Non-lead - Other	No	6" service line		Non-lead - Other	6" service line		Non-Lead		
detected or discovered in any portion of the water specific or discovered in any portion of the water specif												
200505 Fal 22 E PUNALUP, WA, \$8274 Unknown - Unkley lead Don't know Other Den't know Den't know Other Den't know Den't know Other Den't know Den'												
or replacement since the DRIFF to tool over operations of Surjeam. No Lead has very been detected or discovered in on John System. No Lead has very been detected or discovered in on John System. OCOUGE 12015, SN 162 F, FUYALLUP, WA, 98374- DOM'S 1707, SN 162 F, FUYALLUP, WA, 98374-	000095		Unknown - Unlikelv lead	Don't know	Other		Unknown - Unlikelv Lead	Other	portion of the water sysetm	Unknown		
Discrete from the parties of the system. Occord 12015, 58 182 E. PUNALLUP, WA, 28374- Unknown - Unilledy lead Den't know Other Ot		PUYALLUP, WA, 98374-	, , , , , , , , , , , , , , , , , , , ,			or replacement since the	, , , , , , , , , , , , , , , , , , , ,		or replacement since the			
Description of the water system Desc						this system.			of this system.			
Unknown - Unlikely lead Don't know Other through maintenance, repairs or replacement since the District took over operations of this system. Note load has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. Note load has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of the system. Note and has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of the system. Note and has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. Note and has ever been detected or discovered in any portion of the water system of the system. Note and has ever been detected or discovered in any detected or discovered in any portion of the water system. Note and has ever been detected or discovered in any portion of the water system. Note and has ever been detected or discovered in any portion of the water system. Note and has ever been detected or discovered in any portion of the water system. Note and has ever been detected or discovered in any portion of the water system. Note and has ever been detected or discovered in any portion of the water system. Note and has ever been detected or discovered in any portion of the water system. Note and has ever been detected or discovered in any portion of the water system. Note and has ever deen detected or discovered in any portion of the water system of detected or discovered in any portion of the water system. Note and has ever deen detected or discovered in any portion of the water system. Note and has ever deen detected or discovered in any portion of the water system. Note and has ever deen detected or discovered in any portion of the water s						detected or discovered in any			detected or discovered in any			
District took over operations of this system. No Lead has ever been defected or discovered in any partial of the water system through maintenance, repairs or replacement since the District took over operations of the water system. No Lead has ever been defected or discovered in any partial of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system. No Lead has ever been detected or discovered in any partial of the water system through maintenance, repairs or replacement since the District took over operations of the water system. No Lead has ever been detected or discovered in any partial of the water system. No Lead has ever been detected or discovered in any partial of the water system. Unknown - Unlikely Lead Other through maintenance, repairs of the water system. No Lead has ever been detected or discovered in any partial of the water system. No Lead has ever been detected or discovered in any partial of the water system. No Lead has ever been detected or discovered in any partial of the water system. No Lead has ever been detected or discovered in any partial of the water system. No Lead has ever been detected or discovered in any partial of the water system. No Lead has ever been detected or discovered in any partial of the water system. No Lead has ever been detected or discovered in any partial of the water system. No Lead has ever been detected or discovered in any partial of the water system. No Lead has ever been detected or discovered in any partial of the water system. No Lead has ever been detected or discover	000096		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered						District took over operations of			District took over operations			
11707, SR 162 E, PUXALLUP, WA, 98374- O00099 11601, SR 162 E, PUYALLUP, WA, 98374- O00099 11601, SR 162 E, PUYALLUP						No Lead has ever been			No Lead has ever been			
or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system portion of the water system. Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Other Other Other Unknown - Unlikely lead Other Other Other Other Unknown - Unlikely lead Other O	000007		Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm	Unknown - Unlikaly Land	Other	portion of the water sysetm	Haknowa		
No Lead has ever been detected or discovered in any portion of the water sysetm Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Don't know Other District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm Unknown - Unlikely Lead Other Unknown - Unlikely Lead Other Unknown - Unlikely Lead Other No Lead has ever been detected or discovered in any portion of this system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system portion of the water system of this system. Unknown - Unlikely Lead Other Other Unknown - Unlikely Lead Other Other Unknown - Unlikely Lead Other Unknown - Unlikely Lead Other Other Unknown - Unlikely Lead Other Other Unknown - Unlikely Lead Other Other Other Unknown - Unlikely Lead Other Other Other Other Other Unknown - Unlikely Lead Other O	000097	PUYALLUP, WA, 98374-	Onknown - Onlikely ledu	Don t know	Other	or replacement since the	Official - Officery Ledu	Other	or replacement since the	Olikilowii		
11617, SR 162 E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other Through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system Unknown - Unlikely Lead Other Through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system No Lead has ever been detected or discovered in any portion of the water system portion of the water system Unknown - Unlikely Lead Other Through maintenance, repairs or replacement since the Other Other Unknown - Unlikely Lead Other						this system.			of this system.			
11617, SR 162 E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system O00099 11601, SR 162 E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system detected or discovered in any portion of the water system Outhown - Unlikely lead Other through maintenance, repairs or through maintenance, repairs or replacement since the or repl						detected or discovered in any			detected or discovered in any			
Or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the Unknown - Unlikely lead Don't know Other Or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the	000098		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
No Lead has ever been detected or discovered in any portion of the water sysetm 11601, SR 162 E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other Through maintenance, repairs or replacement since the No Lead has ever been detected or discovered in any portion of the water sysetm Unknown - Unlikely Lead Other Unknown - Unlikely Lead Other Unknown - Unlikely Lead Other						District took over operations of			District took over operations			
11601, SR 162 E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Unknown - Unlikely lead Don't know Other Other Unknown - Unlikely Lead Don't know Other Unknown - Unlikely Lead Other						No Lead has ever been			No Lead has ever been			
PUYALLUP, WA, 98374- PUYALLUP, WA, 98374- Or replacement since the Onknown - Unlikely lead Other through maintenance, repairs Or replacement since the Onknown - Unlikely lead Other through maintenance, repairs Or replacement since the		11601, SR 162 E.				portion of the water sysetm			portion of the water sysetm			
District took over operations of District took over operations	000099		Unknown - Unlikely lead	Don't know	Other	or replacement since the	Unknown - Unlikely Lead	Other	or replacement since the	Unknown		
this system. of this system.												

000100	11522, SR 162 E,	Unknown Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm	Unknown Unlikely Lond	Othor	No Lead has ever been detected or discovered in any portion of the water sysetm	Hakrowa		
000100	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don t know	Other	through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000101	12403, SR 162 E (MTR	University Unitingly lead	Don't Imau	Othor	No Lead has ever been detected or discovered in any portion of the water sysetm	Halmanus Halikah Land	Othor	No Lead has ever been detected or discovered in any portion of the water sysetm	Halasaus		
000101	1 OF 2), PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
	11807, SR 162 E,				No Lead has ever been detected or discovered in any portion of the water sysetm			No Lead has ever been detected or discovered in any portion of the water sysetm			
000102	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
	14709, 115 ST CT E,				No Lead has ever been detected or discovered in any portion of the water sysetm		Installation date after lead	, ,			
000103	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the District took over operations of	Non-lead - Other	ban		Unknown		
					this system. No Lead has ever been			No Lead has ever been			
					detected or discovered in any portion of the water sysetm			detected or discovered in any portion of the water sysetm			
000120	14721, 115 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
	101/1EE01, W11, 30374				or replacement since the District took over operations of			or replacement since the District took over operations			
					this system.			of this system.			
					No Lead has ever been detected or discovered in any			No Lead has ever been detected or discovered in any			
000131	14701, 115 ST CT E,	University Unificate Lead	Danit Incom	Other	portion of the water sysetm	Halinavia Halibah Land	Oth su	portion of the water sysetm	Halimania		
000121	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the	Unknown - Unlikely Lead	Other	through maintenance, repairs or replacement since the	Unknown		
					District took over operations of this system.			District took over operations of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any portion of the water sysetm			detected or discovered in any portion of the water sysetm			
000122	14702, 115 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
					or replacement since the District took over operations of			or replacement since the District took over operations			
					this system. No Lead has ever been			of this system. No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000123	14708, 115 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs	Unknown - Unlikely Lead	Other	portion of the water sysetm through maintenance, repairs	Unknown		
	FUTALLUF, WA, 98374-				or replacement since the District took over operations of			or replacement since the District took over operations			
					this system.			of this system.			
					No Lead has ever been detected or discovered in any			No Lead has ever been detected or discovered in any			
000124	14718, 115 ST CT E,	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs	Unknown - Unlikely Lead	Other	portion of the water sysetm through maintenance, repairs	Unknown		
000124	PUYALLUP, WA, 98374-	Olikliowii - Ollikely leuu	Don't know	Guiei	or replacement since the	Olikilowii - Olilikely Leud	Other	or replacement since the	CHRIOWII		
					District took over operations of this system.			District took over operations of this system.			
					No Lead has ever been			No Lead has ever been			
	14720 115 ST CT 5				detected or discovered in any portion of the water sysetm			detected or discovered in any portion of the water sysetm			
000125	14720, 115 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the	Unknown - Unlikely Lead	Other	through maintenance, repairs or replacement since the	Unknown		
					District took over operations of			District took over operations			
					this system.			of this system.			

000126	11521, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000127	14810, 115 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000128	14908, 115 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000129	14916, 115 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000130	11401, 150 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000131	11406, 149 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000132	11402, 149 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000133	11316, 149 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000134	11312, 149 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000135	11308, 149 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		

000136	11303, 149 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000137	11315, 149 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000138	14906, 114 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000139	14910, 114 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000140	11521, 150 AVE E, PUYALLUP, WA, 98374-	Non-lead - Other	Don't know	Service line repair/replacement record	Service line material is Poly Repair/Replacement done on 03/28/2000	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000141	15003, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Mobile home was 1977, Statutory Warranty deed is 2002 when service was installed	Unknown		
000142	14914, 114 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000143	14920, 114 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000144	14919, 114 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000145	14907, 114 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		

000146	14924, 115 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000152	11625, 151 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000153	11707, 151 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000154	11811, 151 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000155	11723, 151 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000156	15121, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000157	15110, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000158	15122, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000159	15002, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.			
000162	15504, 112 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		

					No Lead has ever been						
000163	15411, 112 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000165	15205, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000166	15202, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000167	15206, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000168	15308, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000169	15316, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000170	15320, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000171	11214, 154 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000172	15612, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Other	Service line is Poly. Customer Self Reported	Unknown		
000173	11311, 154 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		

					No Lead has ever been						
000174	11307, 154 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000175	11215, 154 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000176	15315, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000177	15311, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000178	15528, 113 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000179	15503, 114 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000180	15404, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Mobile home was 1961, Quit Claim is 2021 when service was installed	Unknown		
000181	15415, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000182	15414, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000183	15416, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Mobile home was 1979, Statutory Warranty deed is 2002 when service was installed	Unknown		

1.000 1.00						No Lead has ever been			No Lead has ever been			
March Marc												
## AND PROPERTY OF THE PROPERT	000184		Unknown - Unlikely lead	Don't know	Other		Unknown - Unlikely Lead	Other		Unknown		
March Marc		PUYALLUP, WA, 98374-	,									
Part						· ·			· '			
Marie Mari												
Part						No Lead has ever been			No Lead has ever been			
						detected or discovered in any			detected or discovered in any			
Married Marr		15514 116 ST F				portion of the water sysetm						
March Marc	000185		Unknown - Unlikely lead	Don't know	Other		Unknown - Unlikely Lead	Other		Unknown		
March Control Contro						'			· '			
No. 1255, 1987. APPLIED THE STATE OF THE ST												
									oj tilis system.			
March Marc						•						
Service Control Contro	000186		Unknown - Unlikely lead	Don't know	Other		Non-lead - Other			Unknown		
Signature of the same of the s		PUTALLUP, WA, 98374-				or replacement since the		Dun				
Security of Contraction of the C												
Processing No. 1987						·						
1500 15 15 15 15 15 15 1												
Description						· ·			·			
FORMALIN, WA, MARIA CONTROLL MARIAN CO	000187	15602, 116 ST E,	Unknown - Unlikely lead	Don't know	Other		I Inknown - I Inlikely Lead	Other		Unknown		
DOUGHE OF THE CONTROL TO A CONT	000107	PUYALLUP, WA, 98374-	Onknown Onnicely ledd	Don't know	Other		Onknown Onnkery Lead	Other		CHAIGWII		
A Secretary of the control of discovered in any processing of the control o												
Section of the same reports of the control of the same reports of									The state of the s			
Section Section Continue						No Lead has ever been			No Lead has ever been			
Distance - Labelloy (read Committed						· ·			· ·			
Active tool and specimens of the section of the sec		15608. 116 ST E.										
Double of the control	000188		Unknown - Unlikely lead	Don't know	Other		Unknown - Unlikely Lead	Other		Unknown		
A Third Section 1 And A Sectio						· ·						
Monto the over been detected or discovered in any parties of the water system for the system. 11407, 54.15F, EVERALLEY, N.A. 98274 District tools over approximant of the system. 11407, 54.15F, Uniterown - Uniterly lead District tools over approximant of the system. 11407, 54.15F, Uniterown - Uniterly lead District tools over approximant of the system. 11407, 54.15F, Uniterown - Uniterly lead District tools over approximant of the system. 11407, 54.15F, Uniterown - Uniterly lead District tools over approximant of the system. 11407, 54.15F, Uniterown - Uniterly lead District tools over approximant of the system. District tool over approximant of the system. District tools over approximant of the system. District tool over approximant of t												
DOTTON 1142,5 9532 E Unitation w Unitariety lend Don't know District water graftin CONALUTE WA, 98376- DOTTON 1142,5 9532 E Unitation w Unitariety lend Don't know Don						,						
APPALLUP, MA, 9837-4 Dissourn - Unitiesy lead Don't know District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular or replacement since the District rook over operations of substance regular and replacement since regular or replacement since the District rook over operations of substance regular and replacement since regular and results of substance regular and results of sub												
AUTHALLE, WA, 98374 Linksown Linksey lead L		11112 CD 162 F										
Descriptions of Descriptions o	000189		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
No lead has serve been detected of discovered in any portion of the worker system. District took over operations of this system. District took over operations of this system. District took over operations of this system. District took over operations of this system. District took over operations of this system. District took over operations of this system. District took over operations of this system. District took over operations of this system. District took over operations of this system. District took over operations of this system. District took over operations of this system. District took over operations of this system. District took over operations of this system. District took over operations of this system. District took over operations of this system. District took over operations of this system. District took over operations of this system. District took over operations of the work system District took over operations of the work system. D		101ALLO1, WA, 30374				· ·						
Molecule has very been detected or discovered in any portion of the water system to replacement since the District tool over personal replacement of the water system or replacement since the District tool over personal replacement since the District tool over the replacement since the Original States and District the Over the replacement since the Original States and District tool over the replacement since the Original States and District tool over the replacement since the Original States and District tool over the replacement since the Original States and District tool over the replacement since												
detected or discovered in any portion of the water system. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know Direct tool over operations of the System. Don't know - Unlikely lead Don't know - Unlikely lead Don't know - Unlikely lead Don't know - Unlike						,						
11402_SR 182 E, PUTALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other No Load has ever been detected or discovered in ony portion of the water system No Load has ever been detected or discovered in ony portion of the water system No Load has ever been detected or discovered in ony portion of the water system Unknown - Unlikely lead Other Unknown - Unlikely lead Don't know Other No Load has ever been detected or discovered in ony portion of the water system Unknown - Unlikely lead Other Unknown - Unlikely lead Other Unknown - Unlikely lead Other Other												
1100.5 8 124.C. PVYALUP, WA, 98.74- O00191 11303, 59 162 E. PUYALUP, WA, 98.74- O00192 11224, 59 162 E. PUYALUP, WA, 98.774- O00193 11225, 59 162 E. PUYALUP, WA, 98.774- O00193 11225, 59 162 E. PUYALUP, WA, 98.774- O00193 11225, 59 162 E. PUYALUP, WA, 98.774- O00194 11225, 59 162 E. PUYALUP, WA, 98.774- O00195 11225, 59 162 E. PUYALUP, WA, 98.774- O00197 11225, 59 162 E. PUYALUP, WA, 98.774- O00197 11225, 59 162 E. PUYALUP, WA, 98.774- O00198 11225, 59 162 E. PUYALUP, WA, 98.774- O00199 11226, 59 162 E. PUYALUP, WA, 98.774- O00199 11227, 59 162 E. PUYALUP, WA, 98.774- O00199 11228, 59 162 E. PUYALUP, WA, 98.774- O00199 11228, 59 162 E. PUYALUP, WA, 98.774- O00199 11229, 59 162 E. PUYALUP, WA, 98.774- O00199 11220, 59 162 E. PUYALUP, WA						,			· ·			
OCCUPY AND SEASON SEASO	000190		Unknown - Unlikely lead	Don't know	Other		Unknown - Unlikely Lead	Other		Unknown		
No toed has ever been detected or discovered in any portion of the water system. 1330, SR 162 E, PUYALLUP, WA, 98374 Unknown - Unlikely lead Don't know Other through maintenance, repairs or replacement since the District took over operations of this system. No Load has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Load has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Load has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Load has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Load has ever been detected or discovered in any portion of the water system of this system. No Load has ever been detected or discovered in any portion of the water system of the water system. No Load has ever been detected or discovered in any portion of the water system of the water system. No Load has ever been detected or discovered in any portion of the water system of the water system of the water system. No Load has ever been detected or discovered in any portion of the water system or replacement since the District took over operations of Unknown - Unlikely lead Other through maintenance, repairs or replacement since the District took over operations of Unknown - Unlikely lead Other through maintenance, repairs or replacement since the District took over operations of Unknown - Unlikely lead Other through maintenance, repairs or replacement since the District took over operations of Unknown - Unlikely lead Other through maintenance, repairs or replacement since the District took over operations of Unknown - Unlikely lead Other th		PUYALLUP, WA, 98374-				-	·					
No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water syste						District took over operations of			District took over operations			
1303, \$R 162 E, PUTALLUP, WA, 98374- Unknown - Unlikely lead Dan't know Other Unknown - Unlikely lead Dan't know Other Unknown - Unlikely lead Unk									· · · · · · · · · · · · · · · · · · ·			
Double 11303, SR 162 E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other through mointenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system. Unknown - Unlikely lead Don't know Other through mointenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system. Unknown - Unlikely lead Don't know Other through mointenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system. Unknown - Unlikely Lead Other through mointenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in a												
00191 1133, 31 fe £, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the word replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the word expertion of the word												
October 1224, SR 162 E, PUYALLUP, WA, 98374- October 1223, SR 162 E, PUYALLUP, WA, 98374- October 1224, SR 162 E	000191		Unknown - Unlikely lead	Don't know	Other		Unknown - Unlikely lead	Other		Unknown		
District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system detected or discovered in any portion of the water system detected or discovered in any portion of the water system or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of through maintenance, repairs or replacement since the District took over operations of Unknown Unlikely lead Other through maintenance, repairs or replacement since the District took over operations of Unknown Unlikely lead Other through maintenance, repairs or replacement since the District took over operations of Unknown Unlikely lead Other through maintenance, repairs or replacement since the District took over operations of Unknown Unknown	000191	PUYALLUP, WA, 98374-	Onknown - Onlikely leud	DOII CKNOW	Other		Shkhowii - Olinkely leud	Other		CHRIOWII		
No Lead has ever been detected or discovered in any portion of the water system. Unknown - Unlikely lead Don't know Other Through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of through maintenance, repairs or replacement since the District took over operations of through maintenance, repairs or replacement since the District took over operations of through maintenance, repairs or replacement since the District took over operations or replacement since the District took over operations or						· ·						
No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of the water system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of District took over									· ·			
11224, SR 162 E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system Unknown - Unlikely lead Other Other Unknown - Unlikely lead Other Unknown - Unlikely lead Other Other Other Unknown - Unlikely lead Other Other Other Unknown - Unlikely lead Other						No Lead has ever been			No Lead has ever been			
11224, SR 102 E, PUYALLUP, WA, 98374- O00193												
PUYALLUP, WA, 98374- POUTALLUP, WA, 98374- PUYALLUP, WA, 98374-	2224	11224, SR 162 E,		0 "	2.1			2.1				
Or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system 11223, SR 162 E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of District took over operations Unknown - Unlikely lead Other through maintenance, repairs or replacement since the District took over operations	000192		Unknown - Unlikely lead	Don't know	Other		Unknown - Unlikely Lead	Other		Unknown		
this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of the system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of the system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of the system. Unknown - Unlikely lead Other through maintenance, repairs or replacement since the District took over operations of the system.						· ·						
No Lead has ever been detected or discovered in any portion of the water sysetm Unknown - Unlikely lead Don't know Other through maintenance, repairs or replacement since the District took over operations of District took over operations No Lead has ever been detected or discovered in any portion of the water sysetm Unknown - Unlikely lead Other through maintenance, repairs or replacement since the District took over operations of District took over operations												
11223, SR 162 E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Other Unknown - Unlikely lead Other Ot						-						
11223, SR 162 E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Other Unknown - Unlikely lead Other Other Other Other Unknown - Unlikely lead Other O												
000193 11225, SR 1D2 E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other through maintenance, repairs or replacement since the District took over operations of District took over operations		11222 50 162 5				•						
Or replacement since the District took over operations of District took over operations	000193		Unknown - Unlikely lead	Don't know	Other		Unknown - Unlikely lead	Other		Unknown		
		1 0 1ALLOP, WA, 303/4-										
this system. of this system.									The state of the s			
						this system.			of this system.			

					No Lead has ever been			No Lead has ever been			
000194	11205, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of	Unknown - Unlikely lead	Other	detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations	Unknown		
000195	11115, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	of this system.	Unknown		
000196	11122, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000197	11114, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000198	11109, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000199	11002, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000200	11009, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000201	11015, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	,	Unknown		
000202	10906, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000203	15012, 109 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		

					No Lead has ever been detected or discovered in any			No Lead has ever been detected or discovered in any			
000204	10824, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000205	10820, SR 162 E, PUYALLUP, WA, 98374-	Galvanized	Don't know	Service line repair/replacement record	Repair/Replacement done on 01/11/2011	Non-lead - Other	Installation date after lead ban		Non-Lead		
000206	10805, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000207	15210, 106 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000208	11108, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000209	11206, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000210	10811, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000212	15026, 106 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000213	10816, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000214	10723, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000215	10717, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		

					No Lead has ever been detected or discovered in any			No Lead has ever been detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000216	10716, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
	UTALLUP, WA, 30374-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system. No Lead has ever been			of this system. No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	10712, SR 162 E,				portion of the water sysetm			portion of the water sysetm			
000217	10/12, SK 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	,,				or replacement since the			or replacement since the			
					District took over operations of this system.			District took over operations of this system.			
					No Lead has ever been			oj uno systemi			
					detected or discovered in any						
000040	10622, SR 162 E,		0 111	0.1	portion of the water sysetm	N 1 1 01	Installation date after lead	Mobile home was 1983,			
000218	UYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the	Non-lead - Other	ban	Reality Contract is 2002 when service was installed	Unknown		
					District took over operations of			Service was instanca			
					this system.						
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000219	15014, 106 ST E,	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs	Unknown - Unlikely lead	Other	portion of the water sysetm through maintenance, repairs	Unknown		
PL	UYALLUP, WA, 98374-	Cimile III Cimile I i i cad	2011 (11110 11	oune.	or replacement since the	ommeny read	- Curer	or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been detected or discovered in any						
					portion of the water sysetm						
000220	15027, 106 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Non-lead - Other	Installation date after lead ban		Unknown		
1	01ALLOF, WA, 36374-				or replacement since the		Duli				
					District took over operations of this system.						
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	15027, 106 ST E,				portion of the water sysetm			portion of the water sysetm			
000221	UYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the	Unknown - Unlikely lead	Other	through maintenance, repairs or replacement since the	Unknown		
					District took over operations of			District took over operations			
					this system.			of this system.			
								No Lead has ever been			
					Service line material is			detected or discovered in any			
000222	15015, 106 ST E,	Non-lead - Other	Don't know	Service line	Galvanized & Poly	Unknown - Unlikely lead	Other	portion of the water sysetm through maintenance, repairs	Unknown		
PL	UYALLUP, WA, 98374-	100,000		repair/replacement record	Repair/Replacment done 06/02/2023			or replacement since the			
					00/02/2023			District took over operations			
					No Lead has ever been			of this system.			
					detected or discovered in any			No Lead has ever been detected or discovered in any			
	15207, 106 ST E,				portion of the water sysetm			portion of the water sysetm			
000223	15207, 106 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
1	, 11., 555/4				or replacement since the			or replacement since the			
					District took over operations of this system.			District took over operations of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000334	15217, 106 ST E,		Dowlet !	0:1	portion of the water sysetm	Halmann H. E. L.	044	portion of the water sysetm	University		
000224	UYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the	Unknown - Unlikely lead	Other	through maintenance, repairs or replacement since the	Unknown		
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000225	15307, 106 ST E,	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs	Unknown - Unlikely lead	Other	portion of the water sysetm through maintenance, repairs	Unknown		
PL	UYALLUP, WA, 98374-	Chimical Chimical Feder	_ 5 t 5 W		or replacement since the	- Chinacity read		or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			

					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000226	15312, 106 ST E,	Unknown - Unlikely lead	Don't know	Other		Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000220	PUYALLUP, WA, 98374-	Olikilowii - Olilikely ledd	Don't know	Other	through maintenance, repairs	Olikilowii - Olilikely ledd	Other		Olikilowii		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					•			· ·			
	15314. 106 ST E.				portion of the water sysetm			portion of the water sysetm			
000227	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	1017122017 1071, 30374				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					·						
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	15403 106 ST 5				portion of the water sysetm			portion of the water sysetm			
000228	15402, 106 ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98374-	,			or replacement since the	,		or replacement since the			
								The state of the s			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000229	15405, 106 ST E,	Unknown - Unlikely lead	Don't know	Other		Unknown - Unlikely lead	Other	through maintenance, repairs	Hakaowa		
000229	PUYALLUP, WA, 98374-	Olikilowii - Olilikely ledu	DON E KNOW	Other	through maintenance, repairs	Olikilowii - Ollikely ledd	Other		Olikilowii		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					· ·			· ·			
	15419, 106 ST E,				portion of the water sysetm			portion of the water sysetm			
000230	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	FUTALLUF, WA, 38374				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					· ·						
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	15419 106 ST 5				portion of the water sysetm			portion of the water sysetm			
000231	15418, 106 ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98374-				or replacement since the	,		or replacement since the			
								The state of the s			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000222	15502, 106 ST E,	Unknown - Unlikely lead	Don't know	Othor		Unknown Unlikely load	Other		Hakaowa		
000232	PUYALLUP, WA, 98374-	Officiowii - Officely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	GHAHOWH		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					The state of the s						
	15507, 106 ST E,				portion of the water sysetm			portion of the water sysetm			
000233	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	. 51/12201 , 11/1, 303/4				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	15511, 106 ST E,				portion of the water sysetm			portion of the water sysetm			
000234		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98374-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000235	15522, 106 ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000233	PUYALLUP, WA, 98374-	Glikilowii - Glilikely leuu	DOIT CKITOW	Other		STIKITOWIT STITIKETY TEAC	Guiei		CITATIO WIT		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			

No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs under the detected or discovered in any portion of the water system through maintenance, repairs under the detected or discovered in any portion of the water system through maintenance, repairs under the detected or discovered in any portion of the water system through maintenance, repairs under the detected or discovered in any	
15609, 106 ST E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Other Unknown - Unlikely	
O00236 PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead	
PUYALLUP, WA, 98374- Output Don't know Other through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system Unknown - Unlikely lead Don't know Other through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of the water system No Lead has ever been detected or discovered in any portion of the water system Unknown - Unlikely lead Other through maintenance, repairs or this system. Unknown - Unlikely lead Other through maintenance, repairs or the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system detected or discovered in any portion of the water system Unknown - Unlikely lead Other through maintenance, repairs or the District took over operations or through maintenance, repairs or the System detected or discovered in any portion of the water system detected or discovered in any portion of the water system detected or discovered in any portion of the water system detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations or replaceme	
Or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system of this system. No Lead has ever been detected or discovered in any portion of the water system or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system portion of the water system through maintenance, repairs	
District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm Unknown - Unlikely lead Don't know Other District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance of detected or discovered in any portion of the water sysetm detected or discovered in any portion of the water sysetm. No Lead has ever been detected or discovered in any portion of the water sysetm detected or discovered in any portion of the water sysetm detected or discovered in any portion of the water sysetm detected or discovered in any portion of the water sysetm detected or discovered in any portion of the water sysetm through maintenance, repairs unknown - Unlikely lead Don't know Other District took over operations of this system. Unknown - Unlikely lead Other District took over operations of the water sysetm detected or discovered in any portion of the water sysetm through maintenance, repairs Unknown - Unlikely lead Other District took over operations of the water sysetm detected or discovered in any portion of the water sysetm through maintenance, repairs Unknown - Unlikely lead Other Unknown - Unlikely lead	
this system. No Lead has ever been detected or discovered in any portion of the water system Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Don't know Other District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system detected or discovered in any portion of the water system through maintenance, repairs Unknown - Unlikely lead Other No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs Unknown - Unlikely lead Other Unknown - Unlikely lead	
No Lead has ever been detected or discovered in any portion of the water sysetm Unknown - Unlikely lead Don't know Other Oth	
detected or discovered in any portion of the water sysetm Unknown - Unlikely lead Don't know Other Other Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Other Other Unknown - Unlikely lead Other	
15606, 106 ST E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Other Unknown - Unlikely lead Other Other Other Unknown - Unlikely lead Other Other Other Unknown - Unlikely lead Other Othe	
000237	
OU023/ PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm 15710, 106 ST E, PUYALLUP, WA 98374- Unknown - Unlikely lead Don't know Other through maintenance, repairs Unknown - Unlikely lead Other Un	
or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm 15710, 106 ST E, PLYALULP WA 98374- Unknown - Unlikely lead Don't know Other through maintenance, repairs Unknown - Unlikely lead Other through maintenance, repairs Unknown - Unlikely lead Other through maintenance, repairs Unknown	
District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm 15710, 106 ST E, PLYALULP WA 98374- Unknown - Unlikely lead District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs Unknown - Unlikely lead Other District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs Unknown - Unlikely lead Other Unknown - Unlikely lead Other Unknown - Unlikely lead Other	
this system. No Lead has ever been detected or discovered in any portion of the water sysetm 15710, 106 ST E, PLYALULP WA 98374- Unknown - Unlikely lead Don't know Other through maintenance, repairs Odd this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs Unknown - Unlikely lead Other through maintenance, repairs Unknown - Unlikely lead Other through maintenance, repairs	
No Lead has ever been detected or discovered in any portion of the water sysetm 15710, 106 ST E, 000238 PLYALULP WA 98374- Unknown - Unlikely lead Don't know Other through maintenance, repairs No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs Unknown - Unlikely lead Other through maintenance, repairs Unknown - Unlikely lead Other through maintenance, repairs	
detected or discovered in any portion of the water sysetm 15710, 106 ST E, 000238 PLYALULP WA 98374- Unknown - Unlikely lead Don't know Other through maintenance, repairs Unknown - Unlikely lead Other Unknown - Unlikely lead Oth	
15710, 106 ST E, 000238 DIVALUE WA 98374- Unknown - Unlikely lead Don't know Other through maintenance, repairs Unknown - Unlikely lead Other through maintenance, repairs Unknown - Unlikely lead Unk	
000238 T5/10, 106 ST E, Unknown - Unlikely lead Don't know Other through maintenance, repairs Unknown - Unlikely lead Other through maintenance, repairs Unknown - Unlikely lead Unknown	
000238 PLIYALILIP WA 98374- Unknown - Unlikely lead Don't know Other through maintenance, repairs Unknown - Unlikely lead Other Unlikely	
TOTALLOT, WAY, 30014	
or replacement since the or replacement since the	
District took over operations of District took over operations	
this system.	
No Lead has ever been No Lead has ever been	
detected or discovered in any detected or discovered in any	
portion of the water sysetm portion of the water sysetm	
000239 PLIVALITIP WA 98374- Unknown - Unlikely lead Don't know Other through maintenance, repairs Unknown - Unlikely lead Other Unlikely	
or replacement since the or replacement since the	
District took over operations of District took over operations	
this system.	
No Lead has ever been No Lead has ever been	
detected or discovered in any detected or discovered in any	
portion of the water sysetm portion of the water sysetm	
000240 PLIYALILIP WA 98374- Unknown - Unlikely lead Don't know Other through maintenance, repairs Unknown - Unlikely lead Other Unlikely	
or replacement since the or replacement since the	
District took over operations of District took over operations	
this system.	
No Lead has ever been	
detected or discovered in any	
portion of the water sysetm Installation date after lead	
000241	
or replacement since the	
District took over operations of	
this system.	
No Lead has ever been	
15903, 106 ST E, Fire Standby service line detected or discovered in any Installation date after lead	
000241-FSB PUYALLUP, WA, 98374- at this location Unknown - Unlikely lead Don't know Other portion of the water sysetm Non-lead - Other ban	
through maintenance, repairs	
No Lead has ever been No Lead has ever been	
detected or discovered in any detected or discovered in any	
portion of the water sysetm portion of the water sysetm	
000242 PLIVALIUP WA 98374- Unknown - Unikely lead Don't know Uther through maintenance, repairs Unknown - Unikely lead Unknown - Unikely	
or replacement since the or replacement since the	
District took over operations of District took over operations	
this system.	
No Lead has ever been No Lead has ever been	
No Lead has even been	
detected or discovered in any detected or discovered in any	
detected or discovered in any portion of the water sysetm detected or discovered in any portion of the water sysetm	
detected or discovered in any portion of the water sysetm 15908, 106 ST E, 000243 PLYALLUP, WA. 98374- Unknown - Unlikely lead Don't know Other through maintenance, repairs Unknown - Unlikely lead Other through maintenance, repairs Unknown - Unlikely lead Other through maintenance, repairs Unknown - Unlikely lead Other through maintenance, repairs Unknown	
detected or discovered in any portion of the water sysetm detected or discovered in any portion of the water sysetm	
detected or discovered in any portion of the water sysetm 15908, 106 ST E, 000243 PLYALLUP, WA. 98374- Unknown - Unlikely lead Don't know Other through maintenance, repairs Unknown - Unlikely lead Other through maintenance, repairs Unknown - Unlikely lead Other through maintenance, repairs Unknown - Unlikely lead Other through maintenance, repairs Unknown	
detected or discovered in any portion of the water sysetm 15908, 106 ST E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Don't know Don't know Don't know Other Unknown - Unlikely lead Don't know Don't know Other Unknown - Unlikely lead Don't know Don't know Other Unknown - Unlikely lead Other Ot	
detected or discovered in any portion of the water sysetm 15908, 106 ST E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know D	
15908, 106 ST E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Other Unknown - Unlikely lead Other Other Unknown - Unlikely lead Other	
15908, 106 ST E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Other Other Unknown - Unlikely lead Other Other Unknown - Unlikely lead Other Othe	
detected or discovered in any portion of the water sysetm Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Other Other Unknown - Unlikely lead Other Othewore on any portion of the water sysetm Other Othe	
detected or discovered in any portion of the water sysetm Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Other Other Other Other Unknown - Unlikely lead Other	
detected or discovered in any portion of the water sysetm Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Other Unknown - Unlikely lead Other Other Unknown - Unlikely lead Other Unknown - Unlikely lead Other Other Unknown - Unlikely lead Other Other Unknown - Unlikely lead Other Other Other Other Other Other Unknown - Unlikely lead Other	
detected or discovered in any portion of the water sysetm Unknown - Unlikely lead Other	
detected or discovered in any portion of the water sysetm Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Other Unknown - Unlikely lead Other Other Unknown - Unlikely lead Other Unknown - Unlikely lead Other Other Unknown - Unlikely lead Other Other Unknown - Unlikely lead Other Other Other Other Other Other Unknown - Unlikely lead Other	
15908, 106 ST E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Other Unknown - Unlikely lead Other Other No Lead has ever been detected or discovered in any portion of the water system No Lead has ever been detected or discovered in any portion of the water system. Isopol, 106 ST E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Other Other Unknown - Unlikely lead Other Other Unknown - Unlikely lead Other Unknown - Unlikely lead Other Other Unknown - Unlikely lead Other Other Unknown - Unlikely lead Other Other Other Unknown - Unlikely lead Other	
15908, 106 ST E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other District took over operations of the water system Unknown - Unlikely lead Don't know Other District took over operations of the water system Unknown - Unlikely lead Other Unkn	
detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of the water system. 15908, 106 ST E, PUYALLUP, WA, 98374-	
detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of the water system of the water system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of the water system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacem	
detected or discovered in only portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in only portion of the water system. No Lead has ever been detected or discovered in only portion of the water system. No Lead has ever been detected or discovered in only portion of the water system. No Lead has ever been detected or discovered in only portion of the water system. No Lead has ever been detected or discovered in only portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in only portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in only portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in only portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in only portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in only portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in only portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in only portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in only portion of the water system through maintenan	
15908, 106 ST E, PUYALLUP, WA, 98374- Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Don't know Other O	
detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system.	

					No Lord has such been						
000247	15627, 106 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000248	15118, 106 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000249	10802, 159 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000260	10415, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000261	10314, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000262	15008, 102 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000263	15009, 102 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000264	15203, 102 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000265	15304, 102 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000266	10122, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		

000267	10117, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Mobile home was 1964, Statutory Warranty deed is 1999 when service was installed	Unknown		
000269	9916, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000270	9904, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000271	9910, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000272	9808, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000273	15018, 96 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000274	9622, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000275	9710, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000276	9809, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000277	9602, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		

000278	15009, 96 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown	
000279	15015, 96 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Mobile homes were 1970s, Quit Claim was 1998 when service was installed	Unknown	
000280	15207, 96 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown	
000281	15302, 96 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown	
000282	15303, 96 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown	
000283	, 96 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown	
000284	15409, 96 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown	
000285	15502, 96 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been	Unknown	
000285-FSB		tandby service at Unknown - Unlikely lead his location	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of	Unknown - Unlikely lead	Other	detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations	Unknown	
000286	14911, 96 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown	

					No Lead has ever been detected or discovered in any			No Lead has ever been detected or discovered in any			
	15711, 96 ST E,				portion of the water sysetm			portion of the water sysetm			
000287	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
					or replacement since the District took over operations of			or replacement since the District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000288	15509, 96 ST E,	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs	Unknown - Unlikely lead	Other	portion of the water sysetm through maintenance, repairs	Unknown		
000200	PUYALLUP, WA, 98374-	Onknown Onnkery read	Don't know	Guiei	or replacement since the	Ommown Ommery read	Cine	or replacement since the	Onknown		
					District took over operations of			District took over operations			
					this system. No Lead has ever been			of this system. No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	9512, SR 162 E,				portion of the water sysetm			portion of the water sysetm			
000289	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
					or replacement since the District took over operations of			or replacement since the District took over operations			
					this system.			of this system.			
					No Lead has ever been						
					detected or discovered in any portion of the water sysetm			Mobile homes were 1970s,			
000290	15017, 96 ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Non-lead - Other	Installation date after lead	Quit Claim was 1998 when	Unknown		
	PUYALLUP, WA, 98374-				or replacement since the		ban	service was installed			
					District took over operations of this system.						
					No Lead has ever been						
					detected or discovered in any						
000204	15121, 102 ST E,	University University	0 14 1	Oth re	portion of the water sysetm	Non-land Other	Installation date after lead		Halmann		
000291	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the	Non-lead - Other	ban		Unknown		
					District took over operations of						
					this system.						
					No Lead has ever been detected or discovered in any						
	15305, 102 ST E,				portion of the water sysetm		Installation data after load				
000292	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Non-lead - Other	Installation date after lead ban		Unknown		
					or replacement since the District took over operations of						
					this system.						
					No Lead has ever been						
					detected or discovered in any portion of the water sysetm						
000293	15415, 96 ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Non-lead - Other	Installation date after lead		Unknown		
	PUYALLUP, WA, 98374-				or replacement since the		ban				
					District took over operations of this system.						
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000300	14901, 96 ST E,	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm	Unknown - Unlikely Lead	Other	portion of the water sysetm through maintenance, repairs	Unknown		
000300	PUYALLUP, WA, 98374-	Olikilowii - Ollikely leda	Don t know	Other	through maintenance, repairs or replacement since the	Onknown - Onlikely Ledu	Other	or replacement since the	OHKHOWII		
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been detected or discovered in any			No Lead has ever been detected or discovered in any			
	9501, 148 AVE E,				portion of the water sysetm			portion of the water sysetm			
000302	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
					or replacement since the District took over operations of			or replacement since the District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any portion of the water sysetm			detected or discovered in any portion of the water sysetm			
000303	14723, 96 ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98374-				or replacement since the			or replacement since the			
					District took over operations of this system.			District took over operations of this system.			
					uns system.			oj uns system.			

					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000304	14721, 96 ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
000304	PUYALLUP, WA, 98374-	Oliklowii Oliikely lead	Don't know	other		Ominown Omincity Lead	other		CHRIGWII		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000305	9423, 148 AVE E,	Halmanna Halibahaland	D = = !t !== =	046		Halman Halibah Land	046		Links access		
000305	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14620, 96 ST E,				portion of the water sysetm			portion of the water sysetm			
000306	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
	101ALLO1, WA, 38374				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					· ·			2, 22 5,500			
000340	9508, SR 162 E,	Non-local Others	Doubt In-	Service line	Repair/Replacement done	Non load Other	Installation date after lead		Non-Load		
000310	PUYALLUP, WA, 98374-	Non-lead - Other	Don't know	repair/replacement	02/12/2021	Non-lead - Other	ban		Non-Lead		
	, , , , , , , , , , , , , , , , , , , ,			, , ,							
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000311	14909, 96 ST E,	Unknown Unlikaly land	Don't know	Other		Unknown Unlikaly Load	Other		Unknown		
000311	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	DOII UKIIOW	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	CHRIOWII		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					·			No Lead has ever been			
								detected or discovered in any			
					Camilaa lima wantanini in Dalu			· ·			
	9422, SR 162 E,			Service line	Service line material is Poly			portion of the water sysetm			
000312	PUYALLUP, WA, 98374-	Non-lead - Poly	Don't know	repair/replacement	Repair/Replacement done	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
	. 6			repair, repracement	01/25/2000			or replacement since the			
								District took over operations			
								of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	9438, SR 162 E,				portion of the water sysetm			portion of the water sysetm			
000313	PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
	FOTALLOF, WA, 38374-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					-			· · · · · · · · · · · · · · · · · · ·			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	9415, SR 162 E,				portion of the water sysetm			portion of the water sysetm			
000314		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
								The state of the s			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	0402 50 462 5				portion of the water sysetm			portion of the water sysetm			
000315	9402, SR 162 E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	0246 50 462 5				portion of the water sysetm			portion of the water sysetm			
000316	9318, SR 162 E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98374-	Similar Comment, read			or replacement since the			or replacement since the			
					■ I The state of						
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000317	9221, SR 162 E,	Unknown Unlikaly load	Don't know	Other		Unknown - Unlikely load	Othor		Linknown		
000317	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	DOII UKIIOW	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	CHRIOWII		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			

										ı		
200010	9218, SR 162 E,					No Lead has ever been detected or discovered in any portion of the water sysetm			No Lead has ever been detected or discovered in any portion of the water sysetm			
000318	PUYALLUP, WA, 98374-		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
	45004 00 ST 5					No Lead has ever been detected or discovered in any portion of the water sysetm			No Lead has ever been detected or discovered in any portion of the water sysetm			
000319	15001, 90 ST E, PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the District took over operations of	Unknown - Unlikely lead	Other	through maintenance, repairs or replacement since the District took over operations	Unknown		
						this system. No Lead has ever been			of this system. No Lead has ever been			
						detected or discovered in any			detected or discovered in any			
000320	8903, SR 162 E,		Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs	Unknown - Unlikely lead	Other	portion of the water sysetm through maintenance, repairs	Unknown		
000320	PUYALLUP, WA, 98372-		Onknown Ommery lead	DON'T KNOW	other	or replacement since the	Ommown Ommery lead	Cine	or replacement since the	STIKITOWIT		
						District took over operations of this system.			District took over operations			
						No Lead has ever been			of this system. No Lead has ever been			
						detected or discovered in any			detected or discovered in any			
000321	8815, SR 162 E,		Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs	Unknown - Unlikely lead	Other	portion of the water sysetm through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-		,			or replacement since the	,		or replacement since the			
						District took over operations of this system.			District took over operations of this system.			
						cins system			No Lead has ever been			
									detected or discovered in any portion of the water sysetm			
000322	8802, SR 162 E, PUYALLUP, WA, 98374-		Galvanized	Don't know	Service line repair/replacement record	Repair/Replacement done 07/06/2004	Unknown - Unlikely Lead	Other	through maintenance, repairs	Unknown		
	FUTALLUF, WA, 36374-				repair/replacement record	07/00/2004			or replacement since the			
									District took over operations of this system.			
						No Lead has ever been						
	0424 CD 462 5					detected or discovered in any portion of the water sysetm		Installation data often land	Mobile home was 1978, Quit			
000323	9121, SR 162 E, PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Non-lead - Other	Installation date after lead ban	Claim was 1999 when service	Unknown		
						or replacement since the District took over operations of			was installed			
						this system.						
						No Lead has ever been detected or discovered in any			No Lead has ever been detected or discovered in any			
	8409, SR 162 E,					portion of the water sysetm			portion of the water sysetm			
000324	PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the	Unknown - Unlikely lead	Other	through maintenance, repairs or replacement since the	Unknown		
						District took over operations of			District took over operations			
						this system.			of this system. No Lead has ever been			
									detected or discovered in any			
000325	8408, SR 162 E,		Non-lead - Other	Don't know	Service line	Service line material is Poly Repair/Replacement done	Unknown - Unlikely Lead	Other	portion of the water sysetm through maintenance, repairs	Unknown		
000323	PUYALLUP, WA, 98374-		Non-leud - Other	DOIT E KNOW	repair/replacement record	10/12/2022	Olikilowii - Olilikely Ledd	Other	or replacement since the	Olikilowii		
									District took over operations			
									of this system. No Lead has ever been			
	15010 00140					Complete line and the line of			detected or discovered in any			
000330	15910, BOWMAN HILTON RD E,	RV park	Non-lead - Other	No	Other	Service line material is Black Poly Information provided by	Unknown - Unlikely lead	Other	portion of the water sysetm through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-					Valley map (G-2)			or replacement since the			
									District took over operations of this system.			
									No Lead has ever been			
	15910 BOWMAN					Service line material is Rlack			detected or discovered in any			
000331	15910, BOWMAN HILTON RD E,	RV park	Non-lead - Other	No	Other	Service line material is Black Poly Information provided by	Unknown - Unlikely lead	Other		Unknown		
000331		RV park	Non-lead - Other	No	Other		Unknown - Unlikely lead	Other	detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the	Unknown		
000331	HILTON RD E,	RV park	Non-lead - Other	No	Other	Poly Information provided by	Unknown - Unlikely lead	Other	detected or discovered in any portion of the water sysetm through maintenance, repairs	Unknown		

										I		
									No Lead has ever been detected or discovered in any			
	15910, BOWMAN				211	Service line material is Black		0.1	portion of the water sysetm			
000332	HILTON RD E,	RV park	Non-lead - Other	No	Other	Poly Information provided by	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-					Valley map (G-2)			or replacement since the			
									District took over operations			
						No Lead has ever been			of this system. No Lead has ever been			
						detected or discovered in any			detected or discovered in any			
						portion of the water sysetm			portion of the water sysetm			
000333	8106, 157 AVE E,		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-		, , , , , , , , , , , , , , , , , , , ,			or replacement since the	, , , , , , , , , , , , , , , , , , , ,		or replacement since the			
						District took over operations of			District took over operations			
						this system.			of this system.			
						No Lead has ever been			No Lead has ever been			
						detected or discovered in any			detected or discovered in any			
	15636, 80TH ST E,					portion of the water sysetm			portion of the water sysetm			
000334	PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	7 0 17 12201 , 107 1, 30372					or replacement since the			or replacement since the			
						District took over operations of			District took over operations			
						this system.			of this system.			
						No Lead has ever been			No Lead has ever been			
						detected or discovered in any			detected or discovered in any			
000335	15704, 80TH ST E,		Unknown - Unlikely lead	Don't know	Othor	portion of the water sysetm	Halmann Halikalı land	Othor	portion of the water sysetm	Linkanun		
000333	PUYALLUP, WA, 98372-		Offichiown - Officery lead	DON L KNOW	Other	through maintenance, repairs or replacement since the	Unknown - Unlikely lead	Other	through maintenance, repairs or replacement since the	UNKNOWN		
						District took over operations of			District took over operations			
						this system.			of this system.			
						No Lead has ever been			No Lead has ever been			
						detected or discovered in any			detected or discovered in any			
						portion of the water sysetm			portion of the water sysetm			
000336	15716, 80TH ST E,		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-					or replacement since the	·		or replacement since the			
						District took over operations of			District took over operations			
						this system.			of this system.			
						No Lead has ever been			No Lead has ever been			
						detected or discovered in any			detected or discovered in any			
	15724, 80TH ST E,					portion of the water sysetm			portion of the water sysetm			
000337	PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	, , , , , , , , , , , , , , , , , , , ,					or replacement since the			or replacement since the			
						District took over operations of			District took over operations			
						this system.			of this system.			
						No Lead has ever been detected or discovered in any			No Lead has ever been detected or discovered in any			
						portion of the water sysetm			portion of the water sysetm			
000338	15802, 80TH ST E,		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000330	PUYALLUP, WA, 98372-		Ominown Ominery lead	Don't know	other	or replacement since the	ommeny read	Other	or replacement since the	OTHER OWN		
						District took over operations of			District took over operations			
						this system.			of this system.			
						No Lead has ever been			No Lead has ever been			
						detected or discovered in any			detected or discovered in any			
	15808, 80TH ST E,					portion of the water sysetm			portion of the water sysetm			
000339	PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	1					or replacement since the			or replacement since the			
						District took over operations of			District took over operations			
						this system.			of this system.			
						No Lead has ever been			No Lead has ever been			
						detected or discovered in any portion of the water sysetm			detected or discovered in any			
000340	15812, 80TH ST E,		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	portion of the water sysetm	Unknown		
000340	PUYALLUP, WA, 98372-		Olikilowii - Olilikely ledd	DOII (KIIUW	Other	or replacement since the	Olikhowii - Olilikely ledd	Other	through maintenance, repairs or replacement since the	OHKHOWII		
						District took over operations of			District took over operations			
						this system.			of this system.			
						No Lead has ever been			No Lead has ever been			
						detected or discovered in any			detected or discovered in any			
	45024 0074 07 5					portion of the water sysetm			portion of the water sysetm			
000341	15824, 80TH ST E,		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-					or replacement since the			or replacement since the			
						District took over operations of			District took over operations			
						this system.			of this system.			

					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000342	15908, 80TH ST E,	Unknown - Unlikely lead	Don't know	Other		Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000342	PUYALLUP, WA, 98372-	Olikliowii - Olilikely leud	DONTKHOW	Other	through maintenance, repairs	Olikilowii - Olilikely ledd	Other		Olikilowii		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					•			· ·			
	15815, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000343	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	7 0 17 12201 7 17 17 13 37 2				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					-						
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	15403, BOWMAN				portion of the water sysetm			portion of the water sysetm			
000344	HILTON RD E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-	, and the second			or replacement since the	,		or replacement since the			
	7 0 17 12201 7 117 1, 3037 2							The state of the s			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	15403, BOWMAN				portion of the water sysetm			portion of the water sysetm			
000345	HILTON RD E,	Unknown - Unlikely lead	Don't know	Other		Unknown - Unlikely lead	Other	through maintenance, repairs	Hakaowa		
000343		Officiowii - Officely ledd	Don t know	Other	through maintenance, repairs	Offictiowiff - Offiticety ledd	Other		Olkhowii		
	PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					· ·			· ·			
	14921, PIONEER WAY				portion of the water sysetm			portion of the water sysetm			
000347	E, PUYALLUP, WA,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					·						
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	0222 CD 162 F				portion of the water sysetm			portion of the water sysetm			
000348	8222, SR 162 E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-	, and the second se			or replacement since the	,		or replacement since the			
					· ·			The state of the s			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000360	8214, SR 162 E,	Unknown - Unlikely lead	Don't know	Other		Unknown Unlikely load	Other		Hakaowa		
000300	PUYALLUP, WA, 98372-	Officiowii - Officely ledd	Don t know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Olikilowii		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					The state of the s						
	8206, SR 162 E,		- 6.		portion of the water sysetm			portion of the water sysetm			
000361	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	, , , , , , , , , , , , , , , , , , , ,				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14628, PIONEER WAY				portion of the water sysetm			portion of the water sysetm			
000362	E, PUYALLUP, WA,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	2422 6- 1				portion of the water sysetm			portion of the water sysetm			
000363	8120, SR 162 E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000303	PUYALLUP, WA, 98372-	Olikiowi Oliikely ledd	2 SIT CKITOW	Other		Similari Similary ledd	other				
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			

					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000364	8116, SR 162 E,	Unknown Unlikely load	Dan't Imau	Othor		Unknown Unlikely load	Other		Halmanna		
000364	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	, , , , , , , , , , , , , , , , , , , ,				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					·						
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000365	8112, SR 162 E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000303	PUYALLUP, WA, 98372-	Onknown Onnkely lead	DON'T KNOW	Other		Olikilowii Olilikciy icaa	Other		CHRIOWII		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	8104, SR 162 E,				portion of the water sysetm			portion of the water sysetm			
000366		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the	,		or replacement since the			
					· ·			The state of the s			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					· ·						
	14915, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000368	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	FUTALLUF, WA, 98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
								The state of the s			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000369	14908, 80TH ST E,	Unknown Unlikely load	Don't know	Other		Unknown Unlikely load	Other		Linknous		
000369	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	DON EKNOW	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14907, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000370		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-	, , , , , , , , , , , , , , , , , , , ,			or replacement since the	, , , , , , , , , , , , , , , , , , , ,		or replacement since the			
								The state of the s			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					The state of the s						
	14901, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000371	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	1 0 TALLOF, WA, 30372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000372	14818, 80TH ST E,	Unknown - Unlikely lead	Don't know	Other		Unknown - Unlikely lead	Other		Unknown		
000372	PUYALLUP, WA, 98372-	Olikilowii - Olilikely ledd	Don Cknow	Other	through maintenance, repairs	Chknown - Chinkely lead	Other	through maintenance, repairs	GIRHOWII		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14819, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000373		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					· ·						
	14811, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000374	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	1 0 TALLOF, WA, 30372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			

					No Lead has ever been			No Lead has ever been detected or discovered in any			
					detected or discovered in any portion of the water sysetm			portion of the water sysetm			
000375	8010, 148 AVE CT E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-	,			or replacement since the	,		or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000376	8018, 148 AVE E,	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm	Unknown - Unlikely lead	Other	portion of the water sysetm through maintenance, repairs	Hokowa		
000376	PUYALLUP, WA, 98372-	Olikilowii - Olilikely ledd	DOILERIOW	Other	through maintenance, repairs or replacement since the	Officiowii - Officely ledd	Other	or replacement since the	Olikilowii		
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	8011, 148 AVE CT E,		- 1.1	211	portion of the water sysetm		0.1	portion of the water sysetm			
000377	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
					or replacement since the District took over operations of			or replacement since the District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	8017, 148 AVE CT E,				portion of the water sysetm			portion of the water sysetm			
000378	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other		Unknown		
	1 0 m2201 , m, y 50072				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system. No Lead has ever been			of this system. No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000379	8102, 148 AVE CT E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000380	8101, 148 AVE E,	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs	Unknown - Unlikely lead	Other	portion of the water sysetm through maintenance, repairs	Unknown		
000300	PUYALLUP, WA, 98372-	Olikilowii Olilikciy icaa	Don't know	Other	or replacement since the	Chikhowh Chinkely lead	Other	or replacement since the	OTHER OWN		
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000201	8109, 148 AVE E,	Halmanna Halibah Iand	D = = t =	046	portion of the water sysetm	Halmann Halibah land	Oth	portion of the water sysetm	I talaa aaaa		
000381	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the	Unknown - Unlikely lead	Other	through maintenance, repairs or replacement since the	Unknown		
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	8117, 148 AVE CT E,				portion of the water sysetm			portion of the water sysetm			
000382	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
					or replacement since the			or replacement since the			
					District took over operations of this system.			District took over operations of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	9122 149 AVE CT 5				portion of the water sysetm			portion of the water sysetm			
000383	8123, 148 AVE CT E, PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	FUTALLUF, WA, 303/2-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any portion of the water sysetm			detected or discovered in any portion of the water sysetm			
000384	8124, 148 AVE CT E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-			0	or replacement since the	Timely lead	2 3.10.	or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
		-									

					No Lead has ever been			No Lead has ever been			
					detected or discovered in any portion of the water sysetm			detected or discovered in any portion of the water sysetm			
000385	8118, 148 AVE E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-	· ·			or replacement since the	,		or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000386	8001, 147 AVE E,	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm	Unknown - Unlikely lead	Other	portion of the water sysetm through maintenance, repairs	Hakaowa		
000380	PUYALLUP, WA, 98372-	Offictiown - Officery lead	DOII E KIIOW	Other	through maintenance, repairs or replacement since the	Olikilowii - Olliikely leuu	Other	or replacement since the	Olikilowii		
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	8021, 147 AVE E,		- 61	211	portion of the water sysetm		0.1	portion of the water sysetm			
000387	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
					or replacement since the District took over operations of			or replacement since the District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	8113, 147 AVE CT E,				portion of the water sysetm			portion of the water sysetm			
000388	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	7 6 77 12267 7 77 7 9 5 6 7 2				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system. No Lead has ever been			of this system. No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000389	8108, 147 AVE CT E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the	·		or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000390	8112, 147 AVE CT E,	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs	Unknown - Unlikely lead	Other	portion of the water sysetm through maintenance, repairs	Unknown		
000330	PUYALLUP, WA, 98372-	Onknown Chinkely lead	Don't know	Other	or replacement since the	ommeny read	Other	or replacement since the	CHRIOWII		
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000204	14701, PIONEER WAY	University University in a second	Danile language	046	portion of the water sysetm	Halmanna Halibahaland	O+1	portion of the water sysetm	University		
000391	E, PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the	Unknown - Unlikely lead	Other	through maintenance, repairs or replacement since the	Unknown		
	96372-				District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14708, 81 ST CT E,				portion of the water sysetm			portion of the water sysetm			
000392	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
					or replacement since the			or replacement since the			
					District took over operations of this system.			District took over operations of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14710, 81 ST CT E,				portion of the water sysetm			portion of the water sysetm			
000393	14710, 81 ST CT E, PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	1 5 TALLOT , WA, 30372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been detected or discovered in any			No Lead has ever been detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000394	14707, 81 ST CT E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			

					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000395	14709, 81 ST CT E,	Unknown Unlikely load	Don't know	Othor		Unknown Unlikely load	Other		Linkagun		
000393	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	DON L KNOW	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	, , , , , , , , , , , , , , , , , , , ,				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					·						
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000396	14803, 80TH ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000330	PUYALLUP, WA, 98372-	Olikilowii Olilikely ledd	Don't know	Giner		Ommery lead	other		Chancul		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14808, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000397		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
					· ·			· ·			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					· ·			portion of the water sysetm			
000000	14806, 80TH ST E,		5 "	2.1	portion of the water sysetm		0.,				
000398	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	1017122017, 1071, 30372				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
								· · · · · · · · · · · · · · · · · · ·			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000399	14721, 80TH ST E,	Unknown - Unlikely lead	Don't know	Other		Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000399	PUYALLUP, WA, 98372-	Officiowii - Officery fedu	DOIT E KNOW	Other	through maintenance, repairs	Olikliowii - Ollikely ledd	Other		Olikilowii		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14802, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000400		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
					· ·			· ·			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm						
	14715, 80TH ST E,							portion of the water sysetm			
000401	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	. 517LLG1 , 1171, 30372				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000402	14624, 80TH ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other		Unknown		
000402	PUYALLUP, WA, 98372-	Olikilowii - Olilikely leud	Don Cknow	Other		Chknown - Chinkely lead	Other	through maintenance, repairs	GIIKIIOWII		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14623, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000403		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					· ·			The state of the s			
	14617, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000404		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
								The state of the s			
					this system.			of this system.			
								, ,			

## STATE OF												
### PARK TOTAL PROPERTY OF THE						No Lead has ever been			No Lead has ever been			
## PARK TOTAL PROPERTY OF THE						detected or discovered in any			detected or discovered in any			
March Marc						· ·			· ·			
Product of the Control of the Cont	000405	14619, 80TH ST E,	Unknown Unlikely land	Dan't know	Othor		Unknown Unlikely load	Othor		Linkanin		
Book of the set of the	000405	PUYALLUP. WA. 98372-	Unknown - Unlikely ledd	Don t know	Other		Unknown - Unikely lead	Other		Unknown		
Control (1997) Cont		, , , , , , , , , , , , , , , , , , , ,				or replacement since the			or replacement since the			
March Marc						District took over operations of			District took over operations			
March Marc						this system.			of this system.			
Make wilder to the property of						·						
ACCUPATION OF A MATERIAL SURVINOUS CONTROL Control of the Cont												
						detected or discovered in any			detected or discovered in any			
Mile		44620 0074467.5				portion of the water sysetm			portion of the water sysetm			
AND STANDARD BY AND STANDARD B	000406		Unknown - Unlikely lead	Don't know	Other	through maintenance renairs	Unknown - Unlikely lead	Other	through maintenance renairs	Unknown		
March Marc		PUYALLUP, WA, 98372-			2 3.73							
March Control Contro						The state of the s						
March						District took over operations of			District took over operations			
Self-a Bird 16 1. Self-a Bird 1						this system.			of this system.			
Self-a Bird 16 1. Self-a Bird 1						No Lead has ever been			No Lead has ever been			
METAL PRINCIPATE MARINESTE												
Authors Markey						•			· ·			
Months M		14614. 80TH ST E.										
Marie Mari	000407		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
Manual M		FOTALLOF, WA, 38372-				or replacement since the			or replacement since the			
Manual M						District took over operations of			District took over operations			
March of the Composition of Control of Notice of American Application of American Application of Control of Notice of American Application of Control of Notice of American Application of												
Secretary of the control of the cont						· · · · · · · · · · · · · · · · · · ·			· · · · · · · · · · · · · · · · · · ·			
AND SECOND SECON												
Application						detected or discovered in any			detected or discovered in any			
Application						portion of the water sysetm			portion of the water sysetm			
PARTIES AND THE PARTIES AND TH	000408	8019, 146 AVE CT E,	Unknown - Unlikely lead	Don't know	Other		Unknown - Unlikely lead	Other		Unknown		
Decree 1 March	000408	PUYALLUP, WA, 98372-	Olikilowii - Olilikely leud	Don't know	Other		Olikilowii - Olliikely leuu	Other	• • • • • • • • • • • • • • • • • • • •	Olkilowii		
Control Cont												
A STANK, VICE AND TEST OF THE PROPERTY OF THE						District took over operations of			District took over operations			
A STANK, VICE AND TEST OF THE PROPERTY OF THE						this system.			of this system.			
ABAS, 145 AF CT. (RIVALIUP, MA, 5637) ABAS, 145 AF CT. (· ·						
SIND-S. M. MCC II. FUTUUM PIA 2017 SOUTH STATE CONTRIBUTION PIA 2017 SOUTH STATE CO												
October 1997 - Market V. State Comment of the comme						· ·			· ·			
ACMULTIPE WAY, \$63727. Uniforcian - California processor of Communication Services of Service Services and Communication Services of Services Serv		9102-5 146 AVE CT E				portion of the water sysetm			portion of the water sysetm			
Service of the system. 2021-12 APPE CTE. 1221-12	000409		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
Oblit 1 ST. 166 HF CF. APPALLUS NO. 98272. Distriction with a company of the control of the co		PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
Miles of the service						· ·						
No Learn flare serve from partition of the water system. OCIDITATION OF THE PATHOLIST FLARE CONTROLLING MAY 36772- OCIDITATION OF THE PATHOLIST FLARE CONTRO												
## SEEL 16 ARE CET BURGET BY AND FOR THE WAY FOR THE W						this system.			of this system.			
### Particular No. 2001/10 ##						No Lead has ever been			No Lead has ever been			
### Particular No. 2001/10 ##						detected or discovered in any			detected or discovered in any			
OCIVID PURILLIP, WAY, 98.9377- OCIVIT PURILLIP, WAY, 98.9377-						· ·			· ·			
or replacement since the District root over opportunity of Superior and Color of the System. Aless, process NAY 5, Process NAY 6, Process NAY 6, Process NAY 93372. Aless, process NAY 6, Process NAY 6	000410	8111, 146 AVE CT E,	University Delibertational	D = = t	046		Halmanna Halibah land	Oth		Under access		
District of over operations since the District content since the District c	000410	PUYALLUP, WA. 98372-	Unknown - Unlikely lead	Don't know	Otner		Unknown - Unlikely lead	Otner		Unknown		
ABSS_PROMER WAY Dilinown - Unlikely lead Don't know						or replacement since the			or replacement since the			
No Lead has ever been detected of accepted in any portion of the wester system in through monitormore, regains or replacement since the solid discovered in any portion of the wester system in through monitormore, regains or replacement since the solid discovered in any portion of the wester system or replacement since the solid discovered in any portion of the wester system or replacement since the solid discovered in any portion of the wester system or replacement since the solid discovered in any portion of the wester system or replacement since the solid discovered in any portion of the wester system or replacement since the solid discovered in any portion of the wester system of the solid responsibility. The solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the west						District took over operations of			District took over operations			
No Lead has ever been detected of accepted in any portion of the wester system in through monitormore, regains or replacement since the solid discovered in any portion of the wester system in through monitormore, regains or replacement since the solid discovered in any portion of the wester system or replacement since the solid discovered in any portion of the wester system or replacement since the solid discovered in any portion of the wester system or replacement since the solid discovered in any portion of the wester system or replacement since the solid discovered in any portion of the wester system or replacement since the solid discovered in any portion of the wester system of the solid responsibility. The solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the solid discovered in any portion of the wester system of the west						this system.			of this system.			
1615, PONER WAY 002411 F, PUNALLUP, WA, 98372- 100412 P, PUNALUP, W						,						
A SELSE, POLYMELIP, WA, 98372- O'OUTI SELS, POLYMELIP, WA, 98372- O'OUTI SELSE, POLYMELIP, WA, 98372- O'OUTI SELS, POLYMELIP, WA, 98372- O'OUTI SELSE, POLYMELIP, WA, 98372- O'OUTI SELS, POLYMELIP, WA, 98372-												
## PAPALLUP, WA, 98372- ONALITY, WA, 98372- ONALI						The state of the s			detected or discovered in any			
## Season		14615, PIONEER WAY				portion of the water sysetm			portion of the water sysetm			
## Season	000411	E. PUYALLUP. WA.	Unknown - Unlikelv lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
District took over operations of this system. O00412 POS, 146 AVE E, PUTALLUF, WA, 38372- O00413 POS, 146 ST E, PUTALLUF, WA, 38372- O00414 PUTALUF, WA, 38372- O00414 PUTALUF, WA, 38372- O00414 PUTALUF, WA, 38372- O00415 PUTALUF, WA, 38372- O00416 PUTALUF, WA, 38372- O00417 PUTALUF, WA, 38372- O00417 PUTALUF, WA, 38372- O00418 PUTALUF, WA, 38372- O00418 PUTALUF, WA, 38372- O00419												
MS ystem. 1		30372				· ·						
No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement												
POOLITE PUPALLUP, WA, 98372- 14603, 80TH ST E, PUPALLUP, WA, 98372- 14516, 80TH ST E, PUPALLUP, WA, 98372- 14618, 80TH ST E						this system.			of this system.			
POOLITE PUPALLUP, WA, 98372- 14603, 80TH ST E, PUPALLUP, WA, 98372- 14516, 80TH ST E, PUPALLUP, WA, 98372- 14618, 80TH ST E						No Lead has ever been			No Lead has ever been			
POOLIZE TO STAGE AND E PUNALLIP, WA, 98372- DOOLIZE TO STAGE AND E PUNALLIP AND												
O00412 PUXALUP, WA. 98372- O00413 PUXALUP, WA. 98372- O00414 PUXALUP, WA. 98372- O00414 PUXALUP, WA. 98372- O00415 PUXALUP, WA. 98372- O00416 PUXALUP, WA. 98372- O00417 PUXALUP, WA. 98372- O00418 PUXALUP, WA. 98372- O00418 PUXALUP, WA. 98372- O00418 PUXALUP, WA. 98372- O00419 PUXALUP, WA. 98372- O00419 PUXALUP, WA. 98372- O00410 PUXALUP, WA. 98372- O0						The state of the s			The second secon			
Don't know Other through maintenance, repairs or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system for replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system for replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system for replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system for replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system for replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system for the water system detected or discovered in any portion of the water system detected or discovered in any portion of the water system detected or discovered in any portion of the water system for the water system detected or discovered in any portion of the water system or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system detected or discovered in any portion of the water system detected or discovered in any portion of the water system detected or discovered in any portion of the water system detected or discovered in any portion of the water system detected or discovered in any portion of the water system detected or discovered in any portion of the water system detected or discovered in any portion of the water system detected or discovered in any portion of the water system detected or discovered in any portion of the water system detected or discovered in any portion of the water system detected or discovered in any portion of the water system detected or discove	000410	7905, 146 AVE E,		D. 111	0.1		University to the terminal	0.1		University		
O00413 14603,80TH ST E, PUYALLUP, WA, 98372- 000414 14516,80TH ST E, PUYALLUP, WA, 98372- 000414 14516,80TH ST E, PUYALLUP, WA, 98372- 000414 14516,80TH ST E, PUYALLUP, WA, 98372- 000415 14516,80TH ST E, PUYALLUP, WA, 98372- 000416 14516,80TH ST E, PUYALLUP, WA, 98372- 000417 14516,80TH ST E, PUYALLUP, WA, 98372- 000418 14516,80TH ST E, PUYALLUP, WA, 98372- 000419 14516,80TH ST E, PUYALLUP, WA, 98372- 000410 14516,00TH ST E,	000412	PUYALLUP, WA. 98372-	Unknown - Unlikely lead	Don't Know	Otner		Unknown - Unlikely lead	Otner		Uliknown		
No Lead has ever been detected or discovered in any portion of the water system. 14603, 80TH ST E, PUYALLUP, WA, 98372- 000413 14516, 80TH ST E, PUYALLUP, WA, 98372- 000414 14516, 80TH ST E, PUYALLUP, WA, 98372- 000415 14516, 80TH ST E, PUYALLUP, WA, 98372- 000416 14516, 80TH ST E, PUYALLUP, WA, 98372- 000417 14516, 80TH ST E, PUYALLUP, WA, 98372- 000418 14516, 80TH ST E, PUYALLUP, WA, 98372- 000417 14516, 80TH ST E, PUYALLUP, WA, 98372- 000418 14516, 80TH ST E, PUYALLUP, WA, 98372- 000419 14516, 80TH ST E, PUYALLUP, WA, 98372- 0004		, , 555.2							· ·			
No Lead has ever been detected or discovered in any portion of the water system. 14603, 80TH ST E, PUYALLUP, WA, 98372- 000413 14516, 80TH ST E, PUYALLUP, WA, 98372- 000414 14516, 80TH ST E, PUYALLUP, WA, 98372- 000415 14516, 80TH ST E, PUYALLUP, WA, 98372- 000416 14516, 80TH ST E, PUYALLUP, WA, 98372- 000417 14516, 80TH ST E, PUYALLUP, WA, 98372- 000418 14516, 80TH ST E, PUYALLUP, WA, 98372- 000417 14516, 80TH ST E, PUYALLUP, WA, 98372- 000418 14516, 80TH ST E, PUYALLUP, WA, 98372- 000419 14516, 80TH ST E, PUYALLUP, WA, 98372- 0004						District took over operations of			District took over operations			
14603, 80TH ST E, PUYALLUP, WA, 98372- 000414 14516, 80TH ST E, PUYALLUP, WA, 98372- 000415 14516, 80TH ST E, PUYALLUP, WA, 98372- 000416 14516, 80TH ST E, PUYALLUP, WA, 98372- 000417 14516, 80TH ST E, PUYALLUP, WA, 98372- 000418 14516, 80TH ST E, PUYALLUP, WA, 98372- 000419 14516, 80TH ST E, PUYALLU												
14603, 80TH ST E, PUYALLUP, WA, 98372- 14516, 80TH ST E, PUYALLUP, WA, 98372- 14516, 80TH ST E, PUYALLUP, WA, 98372- 14516, 80TH ST E, PUYALLUP, WA, 98372- 15516						-						
14603, 80TH ST E, PUYALLUP, WA, 98372- Unknown - Unlikely lead Don't know Other Don't know Unknown - Unlikely lead Unknown - Unlikely lead Other Don't know Unknown - Unlikely lead Unknown -												
Unknown - Unlikely lead Other Unknown - Unlikely												
Unknown - Unlikely lead Other Unknown - Unlikely		1/602 2074 57 5				portion of the water sysetm			portion of the water sysetm			
PUYALLUP, WA, 98372- On replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system to replacement since the District took over operations of the water system to replacement since the District took over operations of the water system to replacement since the District took over operations of the water system to replacement since the District took over operations of the water system to replacement since the District took over operations of the water system to replacement since the District took over operations of the water system to replacement since the District took over operations of the water system to replacement since the District took over operations of the water system to replacement since the District took over operations of the water system to replacement since the District took over operations of the water system to replacement since the District took over operations of the water system to replacement since the District took over operations of the water system to replacement since the District took over operations of the water system to replacement since the District took over operations of the water system to replacement since the District took over operations of the water system to replacement since the District took over operations of the water system to the District took over operations of the water system to the District took over operations of the water system to the District took over operations of the Water System to the District took over operations of the Water System to the District took over operations of the Water System to the District took over operations of the Water System to the District took over operations of the Water System to the District took over operations of the Water System to the D	000413		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other		Unknown		
District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system portion of the water system portion of the water system of replacement since the District took over operations of District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water system portion of the water system of replacement since the District took over operations of verification of the very operation of the water system of replacement since the District took over operations of very operations of very operation of the very operation of the very operation of the very operation of the very operations of very operation of very operations of very operations of very operation		PUYALLUP, WA, 98372-										
14516, 80TH ST E, PUYALLUP, WA, 98372- PUYALLUP, WA, 98372- PUYALLUP, WA 98372- PUYALL												
No Lead has ever been detected or discovered in any portion of the water sysetm 14516, 80TH ST E, PUYALLUP, WA, 98372- PUYALLUP, WA, 98372- PUYALLUP, WA 98372- PUYALL												
14516, 80TH ST E, PUYALLUP, WA, 98372- Unknown - Unlikely lead Don't know Other through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations or replacement since the District took over operations or replacement since the District took over operations or r						this system.			of this system.			
14516, 80TH ST E, PUYALLUP, WA, 98372- Unknown - Unlikely lead Don't know Other through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water sysetm through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations of the water system through maintenance, repairs or replacement since the District took over operations or replacement since the District took over operations or replacement since the District took over operations or r						No Lead has ever been			No Lead has ever been			
14516, 80TH ST E, PUYALLUP, WA, 98372- Unknown - Unlikely lead Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Don't know Other Unknown - Unlikely lead Other Unknown - Unlikely lead Other through maintenance, repairs or replacement since the District took over operations of District took over operations												
000414 Unknown - Unlikely lead Don't know Other through maintenance, repairs or replacement since the District took over operations of District took over operations						· ·			The second secon			
PUYALLUP, WA, 98372- PUYALLUP, WA, 98372- District took over operations of District took over opera		14516, 80TH ST E.										
or replacement since the District took over operations of District took over operations	000414		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
District took over operations of District took over operations of District took over operations		. OTTLEDT, WA, 30372"				or replacement since the			or replacement since the			
						The state of the s						
uns system.												
						uns system.			oj una system.			

					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000415	7914, 146 AVE E,	Unknown Unlikely load	Don't know	Othor		Unknown Unlikaly load	Othor		Linknous		
000415	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	DON E KNOW	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	, , , , , , , , , , , , , , , , , , , ,				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					·						
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000416	7918, 146 AVE E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000410	PUYALLUP, WA, 98372-	Chikhowh Chinkely lead	Don't know	Giner		Chikhowh Chinkely ledd	Galer		O I I I I I I I I I I I I I I I I I I I		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	7916, 146 AVE E,				portion of the water sysetm			portion of the water sysetm			
000417		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
								· ·			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
								portion of the water sysetm			
	14515, 80TH ST E,		5 6	2.1	portion of the water sysetm		2.1				
000418	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	101ALLO1, WA, 30372				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
								The state of the s			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000419	14509, 80TH ST E,	Unknown Unlikaluland	Don't know	Other		Unknown Unlikely load	Other		Halmanna		
000419	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	DOIT E KNOW	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Olikilowii		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14508, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000420		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-	, , , , , , , , , , , , , , , , , , , ,			or replacement since the	, , , , , ,		or replacement since the			
					· ·			· ·			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14503, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000421	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	FUTALLUP, WA, 303/2-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000422	7906, 146 AVE E,	Unknown Unlikely land	Don't Ima	Other		Unknown Unlikali land	Othor		Linknown		
000422	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	UIIKIIUWII		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	7902, 146 AVE E,				portion of the water sysetm			portion of the water sysetm			
000423		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the	,		or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					· ·						
	7921, 144 AVE CT E,				portion of the water sysetm			portion of the water sysetm			
000427		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
								, ,			

					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000428	7923, 144 AVE CT E,	Unknown Unlikaluland	Don't know	Other		Unknown Unlikely load	Other		Halmanna		
000428	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	DON L KNOW	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	, , , , , , , , , , , , , , , , , , , ,				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					·						
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	0406 444 41/5 5				portion of the water sysetm			portion of the water sysetm			
000429	8106, 144 AVE E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-										
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					•			· ·			
	7900, 146 AVE E,				portion of the water sysetm			portion of the water sysetm			
000430	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	FUTALLUF, WA, 38372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000431	14410, 80TH ST E,	Unknown - Unlikely lead	Don't know	Other		Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000431	PUYALLUP, WA, 98372-	Official - Office of the Contract of the Contr	DON L KNOW	Other	through maintenance, repairs	Unknown - Unikely lead	Other		Unknown		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	1441E 00TU CT E				portion of the water sysetm			portion of the water sysetm			
000432	14415, 80TH ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the	,		or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					· ·			· ·			
	14404, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000433	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	7 0 77 12201 7 117 17 3007 2				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					,						
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000434	8107, 144 AVE E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000-5-	PUYALLUP, WA, 98372-	Ominiown Ominicity ledd	2511 € 10110 ₩	Other		Similari Similariy ieda	- Circi				
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					· ·			The state of the s			
	14401, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000435	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	1 0 TALLUF, WA, 30372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000436	14319, 80TH ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000-30	PUYALLUP, WA, 98372-	Offictiown - Officery ledu	DOIT CKITOW	Other		Olikilowii Olilikely ledd	Other		CXIIOWII		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14312, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000437		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
					The state of the s			The state of the s			
					District took over operations of			District took over operations			
					this system.			of this system.			

					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000438	14313, 80TH ST E,	Unknown - Unlikely lead	Don't know	Other		Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000438	PUYALLUP, WA, 98372-	Olikilowii - Olilikely ledd	Don't know	Other	through maintenance, repairs	Olikilowii - Olilikely ledd	Other		Olikilowii		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					•			· ·			
	14224, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000439	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	7 0 17 12201 7 17 17 30372				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14221 OOTH ST 5				portion of the water sysetm			portion of the water sysetm			
000440	14221, 80TH ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the	,		or replacement since the			
								· ·			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000444	14210, 80TH ST E,		2 11	0.1			0.1				
000441	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14206, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000442		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the	,		or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000443	14203, 80TH ST E,	Unknown - Unlikely lead	Don't know	Other		Unknown - Unlikely lead	Other		Hakaowa		
000443	PUYALLUP, WA, 98372-	Olikilowii - Olilikely ledd	Don t know	Other	through maintenance, repairs	Olikliowii - Ollikely ledd	Other	through maintenance, repairs	Olikilowii		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					The state of the s						
	7815, 142 AVE E,				portion of the water sysetm			portion of the water sysetm			
000444	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	1 JIALLUP, WA, 38372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	7005 442 115 5				portion of the water sysetm			portion of the water sysetm			
000445	7905, 142 AVE E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
330773	PUYALLUP, WA, 98372-	C.Milowii Cimiciy icuu	20 1 111011	Other		Zimiorii Simkely ledd	- Cirici	or replacement since the			
					or replacement since the			·			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000446	14202, 80TH ST E,	Unit to Plant I	D/+ /	0.1		University III II II I	0+1		Halmann		
000446	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	. 51712201 , 1171, 30372				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	1/172 POTU CT F				portion of the water sysetm			portion of the water sysetm			
000447	14123, 80TH ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
					The state of the s			The state of the s			
					District took over operations of			District took over operations			
					this system.			of this system.			

					No Lead has ever been			No Lead has ever been detected or discovered in any			
					detected or discovered in any portion of the water sysetm			portion of the water sysetm			
000448	7910, 142 AVE E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-	,			or replacement since the	,		or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000449	7902, 142 AVE E,	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs	Unknown - Unlikely lead	Other	portion of the water sysetm through maintenance, repairs	Hnknown		
000443	PUYALLUP, WA, 98372-	Olikilowii Olilikely ledd	DOIT CKNOW	Other	or replacement since the	Olikilowii Olilikciy icaa	Other	or replacement since the	OTIKIOWIT		
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000450	7901, 142 AVE E,	Hakaana Halikah laad	Dan't know	Othor	portion of the water sysetm	Unknown Unlikely load	Othor	portion of the water sysetm	Halmanna		
000450	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the	Unknown - Unlikely lead	Other	through maintenance, repairs or replacement since the	Unknown		
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	7822, 142 AVE E,				portion of the water sysetm			portion of the water sysetm			
000451	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	-	Unknown		
					or replacement since the District took over operations of			or replacement since the District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	7725, 142 AVE E,				portion of the water sysetm			portion of the water sysetm			
000459	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
					or replacement since the			or replacement since the			
					District took over operations of this system.			District took over operations of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	7821, 142 AVE E,				portion of the water sysetm			portion of the water sysetm			
000460	7821, 142 AVE E, PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	1011/12/01/, 4471, 30372				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system. No Lead has ever been			of this system. No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000461	7818, 142 AVE E, PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	FOTALLOF, WA, 98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system. No Lead has ever been			of this system. No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	7044 442 41/5 5				portion of the water sysetm			portion of the water sysetm			
000462	7814, 142 AVE E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any portion of the water sysetm			detected or discovered in any portion of the water sysetm			
000463	7607, 142 AVE E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the	2, 1222		or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000464	7716, 142 AVE E,	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs	Unknown - Unlikely lead	Other	portion of the water sysetm through maintenance, repairs	Unknown		
000404	PUYALLUP, WA, 98372-	Olikilowii - Olilikely ledd	DOILCKHOW	Other	or replacement since the	Officiown - Officery lead	Gilei	or replacement since the	OTIKITOWIT		
					District took over operations of			District took over operations			
					this system.			of this system.			
•					· ·			-		•	

					No Lead has ever been			No Lead has ever been		1	
					detected or discovered in any			detected or discovered in any		1	
					portion of the water sysetm			portion of the water sysetm		1	
000465	7717, 142 AVE E,	Unknown Unlikaluland	Don't know	Other		Unknown Unlikely load	Othor		Linkanin	1	
PU!	UYALLUP, WA, 98372-	Unknown - Unlikely lead	DONTKHOW	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown	1	
	, , , , , , , , , , , , , , , , , , , ,				or replacement since the			or replacement since the		1	
					District took over operations of			District took over operations		1	
					this system.			of this system.		1	
					· · · · · · · · · · · · · · · · · · ·						
					No Lead has ever been			No Lead has ever been		1	
					detected or discovered in any			detected or discovered in any		1	
	7002 442 41/5 5				portion of the water sysetm			portion of the water sysetm		1	
000466	7802, 142 AVE E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown	4	
PU	UYALLUP, WA, 98372-			5.51.51	or replacement since the					4	
					The state of the s			or replacement since the		4	
					District took over operations of			District took over operations		4	
					this system.			of this system.		1	
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any		1	
					•			· ·		1	
	14117, 78 ST E,				portion of the water sysetm			portion of the water sysetm		1	
000467	UYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown	1	
FO	OTALLOF, WA, 38372-				or replacement since the			or replacement since the		1	
					District took over operations of			District took over operations		4	
										1	
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000468	14105, 78 ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
PU	UYALLUP, WA, 98372-	Olikilowii - Olilikely leuu	DOII CKIIOW	Other		Official - Officery lead	Other	• • • • • • • • • • • • • • • • • • • •	CHRIOWII		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations		1	
					this system.			of this system.		1	
					No Lead has ever been			No Lead has ever been		1	
										1	
					detected or discovered in any			detected or discovered in any		1	
	14104, 78 ST E,				portion of the water sysetm			portion of the water sysetm		1	
000269		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown	1	
PU	UYALLUP, WA, 98372-				or replacement since the			or replacement since the		4	
										4	
					District took over operations of			District took over operations		1	
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been		1	
					detected or discovered in any			detected or discovered in any		4	
					portion of the water sysetm			portion of the water sysetm		1	
000470	14101, 78 ST E,	Halmanna Halibahaland	D = = 14 1 = - · ·	044		Halmanna Halibah land	Oth		I below soon	1	
000470	UYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown	1	
					or replacement since the			or replacement since the		1	
					District took over operations of			District took over operations		1	
					this system.			of this system.		1	
					No Lead has ever been			No Lead has ever been			
										1	
					detected or discovered in any			detected or discovered in any		1	
7	7010 141CT AVE E				portion of the water sysetm			portion of the water sysetm		1	
000477	7810, 141ST AVE E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown	4	
PU	UYALLUP, WA, 98372-	, , , ,			or replacement since the			or replacement since the			
								· ·			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
7000473	7811, 141ST AVE E,	Undo U. P. I. I.	D==/t-1	0.1		University III II II I	OH.		Halin access		
	UYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Uliknown		
	, , , , , , , , ,				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
7	7810 1/1ST AVE 5				through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000473	7819, 141ST AVE E,	Unknown - Unlikely lead	Don't know	Other						1	
000473	7819, 141ST AVE E, UYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other				or replacement since the			
000473		Unknown - Unlikely lead	Don't know	Other	or replacement since the			or replacement since the			
000473		Unknown - Unlikely lead	Don't know	Other	or replacement since the District took over operations of			District took over operations			
000473		Unknown - Unlikely lead	Don't know	Other	or replacement since the						
000473		Unknown - Unlikely lead	Don't know	Other	or replacement since the District took over operations of			District took over operations			_
000473		Unknown - Unlikely lead	Don't know	Other	or replacement since the District took over operations of this system. No Lead has ever been			District took over operations of this system. No Lead has ever been			
000473		Unknown - Unlikely lead	Don't know	Other	or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any			District took over operations of this system. No Lead has ever been detected or discovered in any			
000473 PU					or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm		Out.	District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm			
000473 PU1	7820, 141ST AVE E,	Unknown - Unlikely lead Unknown - Unlikely lead	Don't know Don't know	Other Other	or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs	Unknown - Unlikely lead	Other	District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs	Unknown		
000473 PU	UYALLUP, WA, 98372-				or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm	Unknown - Unlikely lead	Other	District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm	Unknown		
000473 PU	7820, 141ST AVE E,				or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the		Other	District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs	Unknown		
000473 PU	7820, 141ST AVE E,				or replacement since the District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs		Other	District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the	Unknown		

					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000475	7822, 141ST AVE E,	Unknown Unlikaluland	Don't know	Othor		Unknown Unlikely load	Other		Linknous		
000475	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	DON L KNOW	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	, , , , , , , , , , , , , , , , , , , ,				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					·						
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000476	7824, 141ST AVE E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000470	PUYALLUP, WA, 98372-	Olikilowii Olilikciy icuu	Don't know	Other		Olikilowii Olilikciy icaa	Other		Olikilowii		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	7007 141CT AVE E				portion of the water sysetm			portion of the water sysetm			
000477	7907, 141ST AVE E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-	, and the second se			or replacement since the	,		or replacement since the			
								· ·			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
								•			
	7908, 141ST AVE E,				portion of the water sysetm			portion of the water sysetm			
000478		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					· ·			· ·			
	7912, 141ST AVE E,				portion of the water sysetm			portion of the water sysetm			
000479	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	FUTALLUF, WA, 38372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000480	14101, 80TH ST E,	Unknown Unlikely load	Don't know	Other		Unknown - Unlikely lead	Other		Halmanna		
000480	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	DON L KNOW	Other	through maintenance, repairs	Unknown - Unikely lead	Other	through maintenance, repairs	Unknown		
	, , , , , , , , , , , , , , , , , , , ,				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14036 0071157.5				portion of the water sysetm			portion of the water sysetm			
000481	14026, 80TH ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-	Zimitin Orimery icau		- 1							
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					· ·			The state of the s			
	14106, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000482	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	FUTALLUP, WA, 98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000402	14115, 80TH ST E,	Halmann Hallish Israel	Don't ling	Oth - :		Unknown Unlikelisteral	Othor		Linknown		
000483	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Ulikilowii		
	, , , , , , , , , , , , , , , , ,				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000484	14118, 80TH ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000707	PUYALLUP, WA, 98372-	Chillown Chilicity ledd	DOI! CKNOW	Other		Similari Simkely ledd	Guici				
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			

					No Lead has ever been detected or discovered in any			No Lead has ever been detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000485	14110, 80TH ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the	,		or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14021, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000486	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	7 6 77 12207 7 477 1, 3037 2				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any portion of the water sysetm			detected or discovered in any			
000487	14015, 80TH ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	portion of the water sysetm through maintenance, repairs	Hnknown		
000487	PUYALLUP, WA, 98372-	Olikilowii - Olilikely ledd	DOIT E KITOW	Other	or replacement since the	Olikilowii - Olilikely ledd	Other	or replacement since the	Olikilowii		
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14022 0071157.5				portion of the water sysetm			portion of the water sysetm			
000488	14022, 80TH ST E, PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUTALLUP, WA, 98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
000400	14020, 80TH ST E,		5 //	0.1	portion of the water sysetm		0.1	portion of the water sysetm			
000489	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
					or replacement since the			or replacement since the			
					District took over operations of this system.			District took over operations of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000490	14003, 80TH ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14012, 80TH ST E,		- 6.1	2.1	portion of the water sysetm		0.1	portion of the water sysetm			
000491	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system. No Lead has ever been			of this system. No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000492	14002, 80TH ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-				or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	14001, 80TH ST E,				portion of the water sysetm			portion of the water sysetm			
000493	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any portion of the water sysetm			detected or discovered in any portion of the water sysetm			
000500	7921, 139 AVE CT E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
00000	PUYALLUP, WA, 98372-	Chillown Children lead	DON CKNOW	Other	or replacement since the	Jimilowii Jimikely leud	Other	or replacement since the	CIOWII		
					District took over operations of			District took over operations			
					this system.			of this system.			
					syste			2, 22 3,000			

						No lond has such been			No Lond has aven have			
						No Lead has ever been			No Lead has ever been			
						detected or discovered in any			detected or discovered in any			
000502	13920, 80TH ST E,		Unknown Unlikely load	Don't know	Othor	portion of the water sysetm	Hakaawa Halikah laad	Othor	portion of the water sysetm	Halmania		
000502	PUYALLUP, WA, 98372-		Unknown - Unlikely lead	DON EKNOW	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Onknown		
						or replacement since the			or replacement since the			
						District took over operations of			District took over operations			
						this system.			of this system.			
						No Lead has ever been			No Lead has ever been			
						detected or discovered in any			detected or discovered in any			
000503	13925, 80TH ST E,		Unknown Unlikely load	Don't know	Othor	portion of the water sysetm	Hakaawa Halikah laad	Othor	portion of the water sysetm	Halmanna		
000503	PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
						or replacement since the District took over operations of			or replacement since the			
						this system.			District took over operations of this system.			
						No Lead has ever been			No Lead has ever been			
						detected or discovered in any			detected or discovered in any			
						portion of the water sysetm			portion of the water sysetm			
000504	13912, 80TH ST E,		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Hnknown		
000304	PUYALLUP, WA, 98372-		Olikilowii - Olilikely ledd	DOIT CKNOW	Other	or replacement since the	Olikilowii - Olilikely ledd	Other	or replacement since the	Olikilowii		
						District took over operations of			District took over operations			
						this system.			of this system.			
						No Lead has ever been			No Lead has ever been			
						detected or discovered in any			detected or discovered in any			
						portion of the water sysetm			portion of the water sysetm			
000505	7915, 139 AVE CT E,		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
500505	PUYALLUP, WA, 98372-		Chinical in Chinical redu	2 on Chilow	Other	or replacement since the	OO.III OIIIKEIY ICUU	Other	or replacement since the			
						District took over operations of			District took over operations			
						this system.			of this system.			
						No Lead has ever been			No Lead has ever been			
						detected or discovered in any			detected or discovered in any			
						portion of the water sysetm			portion of the water sysetm			
000506	13906, 80TH ST E,		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-		,			or replacement since the	,		or replacement since the			
						District took over operations of			District took over operations			
						this system.			of this system.			
						No Lead has ever been			No Lead has ever been			
						detected or discovered in any			detected or discovered in any			
	42740 COTU CT F					portion of the water sysetm			portion of the water sysetm			
000508	13719, 80TH ST E,		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-					or replacement since the			or replacement since the			
						District took over operations of			District took over operations			
						this system.			of this system.			
						No Lead has ever been						
						detected or discovered in any						
	14111, PIONEER WAY					portion of the water sysetm		Installation date after lead				
000509	E, PUYALLUP, WA,		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Non-lead - Other	ban		Unknown		
	98372-					or replacement since the		Duit				
						District took over operations of						
						this system.						
						No Lead has ever been						
	14111, PIONEER WAY	Fire Standby				detected or discovered in any		Installation data after I				
000509-FSB	E, PUYALLUP, WA,	Fire Standby service at	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm	Non-lead - Other	Installation date after lead		Unknown		
	98372-	this location				through maintenance, repairs		ban				
						or replacement since the						
						District took over operations of No Lead has ever been			No Lead has ever been			
						detected or discovered in any			detected or discovered in any			
	14201, PIONEER WAY					portion of the water sysetm			portion of the water sysetm			
000510	E, PUYALLUP, WA,		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000010	98372-		Sindlewii Clinkely ledd	DOIT CKNOW	Other	or replacement since the	CHRISTI CHIRCIY ICUU	Other	or replacement since the	C		
	30372					District took over operations of			District took over operations			
						this system.			of this system.			
						No Lead has ever been			No Lead has ever been			
						detected or discovered in any			detected or discovered in any			
	14207, PIONEER WAY					portion of the water sysetm			portion of the water sysetm			
000511	E, PUYALLUP, WA,		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
333311	98372-			20 C KITOW	- Concr	or replacement since the	- Innierry redu	- Curer	or replacement since the			
	2.3/2					District took over operations of			District took over operations			
						this system.			of this system.			
						oyote.m			2, 2,50 0,0001111			

000512	14205, PIONEER WAY E, PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000513	14224, PIONEER WAY E, PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
000514	14404, PIONEER WAY E, PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Mobile home was 1979, Statutory Warranty deed is 1997 when service was installed	Unknown		
000516	14501, PIONEER WAY E, PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely Lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.			
000518	14515, PIONEER WAY E, PUYALLUP, WA, 98372-		Non-lead - Other	No	Installation date after lead ban	Service line material is DI Information provided by VWD map (A-2)	Non-lead - Other	Installation date after lead ban	Service line is Poly Information provided by VWD map (A-2)	Non-Lead		
000518-FSB	14515, PIONEER WAY E, PUYALLUP, WA, 98372-	Fire Standby service at this location	Non-lead -Other	No	Installation date after lead ban	Service line material is DI Information provided by VWD map (A-2)	Non-lead - Other	Installation date after lead ban	Service line is Poly Information provided by VWD map (A-2)	Non-Lead		
000519	14523, PIONEER WAY E, PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000520	14706, PIONEER WAY E, PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.			
000521	14628, PIONEER WAY E, PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.			
000522	14708, PIONEER WAY E, PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.			
000530	14808, PIONEER WAY E, PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.			

000540	14505, MILITARY RD E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000541	14501, MILITARY RD E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000542	14407, MILITARY RD E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm	Unknown - Material Unknown		No meter at this service	Unknown		
000544	14315, PIONEER WAY E, PUYALLUP, WA, 98372-	Non Lead - Plastic	No	Installation date after lead ban	Information provided by Valley map (B-4)	Non Lead - Plastic	Installation date after lead ban	Customer also self reported that material is poly. Installed in 1996 or 1998	Non-Lead		
000545	14319, MILITARY RD E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000546	14305, MILITARY RD E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000547	14221, MILITARY RD E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	oj una ojstem	Unknown		
000548	14211, MILITARY RD E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000549	14119, MILITARY RD E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
000550	13615, PIONEER WAY E, PUYALLUP, WA, 98372-	Non Lead - Plastic	No	Installation date after lead ban	Information provided by Valley map (B-4) Meter Removed	Non Lead - Other	Service line completely removed currently during Pioneer Logistics DE work		Non-Lead		
000551	8515, 146 AVE CT E, PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		

					No Lead has ever been						
					detected or discovered in any						
					portion of the water sysetm						
000552	8502, 146 AVE CT E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Non-lead - Other	Installation date after lead		Unknown		
000002	PUYALLUP, WA, 98372-	Cinatown Cinacity lead	20.7 € 10.70 11	ou.e.		Trom read States	ban				
					or replacement since the						
					District took over operations of						
					this system.						
					No Lead has ever been						
					detected or discovered in any						
					· ·						
	8518, 146 AVE CT E,		_ ,,	2.1	portion of the water sysetm		Installation date after lead				
000553	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Non-lead - Other	ban		Unknown		
	7 6 77 12267 7 177 9 5 6 7 2				or replacement since the		24				
					District took over operations of						
					this system.						
					No Lead has ever been						
					detected or discovered in any						
	8410, 146 AVE CT E,				portion of the water sysetm		Installation date after lead				
000554	PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Non-lead - Other	ban		Unknown		
	PUTALLUP, WA, 98372-				or replacement since the		Dan				
					District took over operations of						
					this system.						
					·						
					No Lead has ever been						
					detected or discovered in any						
	14223, PIONEER WAY				portion of the water sysetm			Customer self reported that			
000555	E, PUYALLUP, WA,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Non-lead - Other	Other	material is poly. Installed in	Unknown		
	98372-				or replacement since the			1996 or 1998			
					District took over operations of						
					this system.			No Lord her			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
	4010 BIONEER WAYE				portion of the water sysetm			portion of the water sysetm			
000596	4010, PIONEER WAY E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-	, and the second se			or replacement since the	,		or replacement since the			
					District took over operations of			District took over operations			
								· ·			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000598	8110, 144 AVE CT E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-	,			or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000599	8111, 144 AVE CT E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000333	PUYALLUP, WA, 98372-	Child Will Chillien	Bon t know	o their	or replacement since the	Chikhowh Chinkely lead	o their		Cincio Wii		
					' ·			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000600	8015, 144 AVE CT E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
000000	PUYALLUP, WA, 98372-	Olikilowii - Olilikely ledd	DOIL CKIIUW	Other		Onknown - Onnkery lead	Other		CHRIOWII		
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been			No Lead has ever been			
					detected or discovered in any			detected or discovered in any			
					portion of the water sysetm			portion of the water sysetm			
000601	8114, 144 AVE CT E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
550001	PUYALLUP, WA, 98372-	Chillown Chillery ledd	20 1 111011	Cirier		Similari Similary icuu	O SHEF				
					or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system.			of this system.			
					No Lead has ever been						
					detected or discovered in any						
					portion of the water sysetm						
000602	3702, PIONEER WAY E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Non-lead - Other	Installation date after lead		Unknown		
00002	PUYALLUP, WA, 98372-	Official Charles Court	Don t Know	Circi			ban				
					or replacement since the						
					District took over operations of						
					this system.						
	14021, PIONEER WAY			Service line	Service line material is Poly		Service line completely				
000603	E, PUYALLUP, WA,	Non-lead - Other	Don't know		Repair/Replacement done on	Non-lead Other	removed currently during		Non-Lead		
	98372-			repair/replacement record	07/25/2000		Pioneer Logistics DE work				
					,, 2000		J LIGIOUGO DE MOIR				

						No Lead has ever been detected or discovered in any			No Lead has ever been detected or discovered in any			
000604	7807, 142 AVE E, PUYALLUP, WA, 98372-	Unknown -	Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs	Unknown - Unlikely lead	Other	portion of the water sysetm through maintenance, repairs	Unknown		
						or replacement since the District took over operations of this system.			or replacement since the District took over operations of this system.			
						No Lead has ever been detected or discovered in any			No Lead has ever been detected or discovered in any			
000605	7917, 144 AVE CT E, PUYALLUP, WA, 98372-	Unknown -	· Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs	Unknown - Unlikely lead	Other	portion of the water sysetm through maintenance, repairs	Unknown		
	FUTALLUF, WA, 90372-					or replacement since the District took over operations of			or replacement since the District took over operations			
						this system. No Lead has ever been detected or discovered in any			of this system. No Lead has ever been			
000606	7915, 144 AVE CT E,	Unknown -	· Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs	Unknown - Unlikely lead	Other	detected or discovered in any portion of the water sysetm through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98372-		ŕ			or replacement since the District took over operations of	·		or replacement since the District took over operations			
						this system. No Lead has ever been			of this system. No Lead has ever been			
000607	7914, 144 AVE CT E,	I Inknown -	· Unlikely lead	Don't know	Other	detected or discovered in any portion of the water sysetm through maintenance, repairs	Unknown - Unlikely lead	Other	detected or discovered in any portion of the water sysetm through maintenance, repairs	Unknown		
000007	PUYALLUP, WA, 98372-	o maio un	onnicity icad	Don't know	other	or replacement since the District took over operations of	onknown onmery read	Cinci	or replacement since the District took over operations	ondia.		
						this system. No Lead has ever been			of this system. No Lead has ever been			
000608	7916, 144 AVE CT E,	Unknown	· Unlikely lead	Don't know	Other	detected or discovered in any portion of the water sysetm	Unknown Unklah land	Other	detected or discovered in any portion of the water sysetm	Halaawa		
000008	PUYALLUP, WA, 98372-	Ulikilowii -	Offitkery ledu	DON EKNOW	Other	through maintenance, repairs or replacement since the District took over operations of	Unknown - Unlikely lead	Other	through maintenance, repairs or replacement since the District took over operations	Olikilowii		
						this system. No Lead has ever been			of this system.			
000609	9515, 148 AVE E,	Unknown	Halikah, laad	Don't know	Othor	detected or discovered in any portion of the water sysetm	Non-land Other	Installation date after lead	Mobile home was 1984, Quit Claim in 2008 when service	Unknown		
000009	PUYALLUP, WA, 98374-	Ulikilowii -	· Unlikely lead	DON EKNOW	Other	through maintenance, repairs or replacement since the District took over operations of	Non-lead - Other	ban	was installed	Olikilowii		
						this system. No Lead has ever been			No Lead has ever been			
000610	8124, SR 162 E,	Unknown -	· Unlikely lead	Don't know	Other	detected or discovered in any portion of the water sysetm through maintenance, repairs	Unknown - Unlikely lead	Other	detected or discovered in any portion of the water sysetm	Haknowa		
000610	PUYALLUP, WA, 98372-	Unknown -	- Оппкету теши	DON EKNOW	Other	or replacement since the District took over operations of	Onknown - Omikely ledd	Other	through maintenance, repairs or replacement since the District took over operations	Unknown		
	14320, PIONEER WAY				Installation date after lead	this system. Information provided byValley		Installation date after lead	of this system.			
001002	E, PUYALLUP, WA, 98372-	Non Lea	ad - Plastic	No	ban	map (B-4) No Lead has ever been	Non Lead - Plastic	ban		Non-Lead		
	10204 150 AV5 CT 5					detected or discovered in any portion of the water sysetm		landalladian dada aftan land				
001055	10304, 150 AVE CT E, PUYALLUP, WA, 98374-	Unknown -	Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the	Non-lead - Other	Installation date after lead ban		Unknown		
						District took over operations of this system. No Lead has ever been						
	10310, 150 AVE CT E,					detected or discovered in any portion of the water sysetm		Installation date after lead				
001056	PUYALLUP, WA, 98374-	Unknown -	· Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the	Non-lead - Other	ban		Unknown		
						District took over operations of this system. No Lead has ever been						
	10314, 150 AVE CT E,					detected or discovered in any portion of the water sysetm		Installation date after lead				
001057	PUYALLUP, WA, 98374-	Unknown -	· Unlikely lead	Don't know	Other	through maintenance, repairs or replacement since the District took over operations of	Non-lead - Other	ban		Unknown		
						this system.						

					No Lead has ever been					
001058	10317, 150 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001060	10309, 150 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001061	10303, 150 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001062	10302, 151 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001063	10308, 151 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001065	10316, 151 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001067	10307, 151 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001068	10301, 151 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001069	10215, 151 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001070	10207, 151 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		

					No Lead has ever been detected or discovered in any					
001071	10208, 151 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001072	10206, 151 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of	Non-lead - Other	Installation date after lead ban	Unknown		
001073	10214, 151 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001074	15101, 103 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001075	15015, 103 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001076	15007, 103 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001077	10315, 151 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001078	10313, 150 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001079	10314, 151 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001101	14210, 125 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		

					No Lead has ever been detected or discovered in any					
001102	14204, 125 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001103	14202, 125 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001104	12506, 142 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001105	12502, 142 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001106	12416, 142 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001107	12412, 142 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001108	12408, 142 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001109	12404, 142 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001110	14201, 124 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001111	14205, 124 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		

					No Lead has ever been detected or discovered in any						
001112	14211, 124 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001113	14215, 124 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the	Non-lead - Other	Installation date after lead ban		Unknown		
					District took over operations of this system.						
001114	14301, 124 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001115	12409, 143 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001116	12415, 143 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001117	12417, 143 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001118	12419, 143 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001119	14306, 125 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001120	14302, 125 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001121	14216, 125 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		

001122	14213, 125 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the	Non-lead - Other	Installation date after lead ban	Unknown		
001123	12501, 142 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	District took over operations of this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the	Non-lead - Other	Installation date after lead ban	Unknown		
					District took over operations of this system. No Lead has ever been detected or discovered in any					
001124	12415, 142 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001125	12413, 142 AVE E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001126	14206, 124 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001127	12410, 143 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001128	12416, 143 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001129	12418, 143 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001130	12413, 143 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001131	14307, 124 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		

001132	12406, 143 AVE CT E, PUYALLUP, WA, 98374-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001133	12417, 143 AVE CT E, PUYALLUP, WA, 98374-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001134	12416, 143 AVE CT E, PUYALLUP, WA, 98374-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001135	12412, 143 AVE CT E, PUYALLUP, WA, 98374-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001136	12407, 143 AVE CT E, PUYALLUP, WA, 98374-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001137	12421, 143 AVE CT E, PUYALLUP, WA, 98374-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001138	14310, 125 ST CT E, PUYALLUP, WA, 98374-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001139	14314, 125 ST CT E, PUYALLUP, WA, 98374-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001140	14311, 124 ST CT E, PUYALLUP, WA, 98374-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001141	12420, 143 AVE CT E, PUYALLUP, WA, 98374-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001200		XXXX PARK METER, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Park meter	Non-Lead		

	15002 87 ST CT E,			Installation date after lead	Service line material is poly		Installation date after lead			
001201	PUYALLUP, WA, 98372-	Non-lead - Other	No	ban	Information provided by Valley map (C-5)	Non-lead - Other	ban	Non-Lead		
001202	15006 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001203	15012 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001204	15104 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001205	15110 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001206	15116 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001207	15204 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001208	15206 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001209	15212 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead ban	Non-Lead		
001210	15218 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead	Non-Lead		
001211	15302 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead ban	Non-Lead		
001212	15306 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	map (C-5) Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001213	15315 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001214	15309 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001215	8715 153 AVE E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001216	8707 153 AVE E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead ban	Non-Lead		
001217	8617 153 AVE E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	map (C-5) Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001218	8611 153 AVE E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead ban	Non-Lead		
001219	8603 153 AVE E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead ban	Non-Lead		
001220	8519 153 AVE E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	map (C-5) Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001221	8515 153 AVE E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead ban	Non-Lead		
001222	8507 153 AVE E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead ban	Non-Lead		
001223	8501 153 AVE E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead	Non-Lead		
001224	8415 153 AVE E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead ban	Non-Lead		
					map (C-5)					

001226 8407 153	2, WA, 98372- 53 AVE E.	Non-lead - Other	No	la ava	Information provided by Valley	Non-lead - Other		I IN			
1 001226	53 AVE E.			ban	map (C-5)		ban		on-Lead		
	P, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	N	on-Lead		
001227	53 AVE E, 2, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	N	on-Lead		
001228	53 AVE E, P, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	N	on-Lead		
1 001229	53 AVE E, 2, WA, 98372-	Non-lead - Other	No	Installation date after lead	Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead	N	on-Lead		
001230 8410 153	53 AVE E, D, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead	N	on-Lead		
001231 8412 153	53 AVE E,	Non-lead - Other	No	Installation date after lead	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead	N	on-Lead		
001232 8416 153	53 AVE E,	Non-lead - Other	No	ban Installation date after lead	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	ban Installation date after lead	N	lon-Lead		
PUYALLUP, V	52 AVE E,			ban Installation date after lead	map (C-5) Service line material is poly		ban Installation date after lead				
001233 PUYALLUP, V	P, WA, 98372-	Non-lead - Other	No	ban	Information provided by Valley map (C-5) Service line material is poly	Non-lead - Other	ban	N	on-Lead		
001234	52 AVE E, 2, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	N	on-Lead		
1 001235	52 AVE E, P, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	N	on-Lead		
1 001236	52 AVE E, P, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	N	on-Lead		
001237	52 AVE E, P, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	N	on-Lead		
001238	52 AVE E, P, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	N	on-Lead		
001239	52 AVE E, 2, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead	N	on-Lead		
001240 8406 152	52 AVE E, D, WA, 98372-	Non-lead - Other	No	Installation date after lead	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead	N	on-Lead		
001241 8408 152	52 AVE E, P, WA, 98372-	Non-lead - Other	No	Installation date after lead	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead	N	on-Lead		
001242 8410 152	52 AVE E, D, WA, 98372-	Non-lead - Other	No	Installation date after lead	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead	N	on-Lead		
001245 8506 150	50 AVE E,	Non-lead - Other	No	Installation date after lead	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead	N	on-Lead		
001246 8510 150	7, WA, 98372- 50 AVE E,	Non-lead - Other	No	ban Installation date after lead	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	ban Installation date after lead	N	on-Lead		
PUYALLUP, V	50 AVE E,			ban Installation date after lead	map (C-5) Service line material is poly		ban Installation date after lead				
PUYALLUP, V	P, WA, 98372-	Non-lead - Other	No	ban	Information provided by Valley map (C-5) Service line material is poly	Non-lead - Other	ban	N	on-Lead		
1 001250	50 AVE E, D, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	N	on-Lead		
001251	50 AVE E, P, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	N	on-Lead		
001757	50 AVE E, P, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	N	on-Lead		

001253	8712 150 AVE E,	Non-lead - Other	No	Installation date after lead	Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead	Non-	-Lead		
001233	PUYALLUP, WA, 98372-	Non-leuu - Other	140	ban	map (C-5)	Non-ledu - Other	ban	Non-	-Leau		
001254	15013 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-	-Lead		
001255	15103 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-	-Lead		
001256	15109 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead ban	Non-	-Lead		
001258	15203 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead	Non-	-Lead		
001259	15207 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead	Non-	-Lead		
001260	15213 87 ST CT E,	Non-lead - Other	No	Installation date after lead	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead	Non-	-Lead		
	PUYALLUP, WA, 98372- 15216 87 ST E,			ban Installation date after lead	map (C-5) Service line material is poly		ban Installation date after lead				
001261	PUYALLUP, WA, 98372-	Non-lead - Other	No	ban	Information provided by Valley map (C-5) Service line material is poly	Non-lead - Other	ban	Non-	-Lead		
001262	15210 87 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (C-5) Service line material is poly	Non-lead - Other	Installation date after lead ban	Non-	-Lead		
001263	15202 87 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-	-Lead		
001264	15112 87 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-	-Lead		
001265	15108 87 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-	-Lead		
001266	15102 87 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-	-Lead		
001267	15018 87 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-	-Lead		
001268	15019 87 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead	Non-	-Lead		
001269	15101 87 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead	Non-	-Lead		
001270	15107 87 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead	Non-	-Lead		
001271	15111 87 ST E,	Non-lead - Other	No	Installation date after lead	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	Installation date after lead	Non-	-Lead		
001272	PUYALLUP, WA, 98372- 15201 87 ST E,	Non-lead - Other	No	ban Installation date after lead	map (C-5) Service line material is poly Information provided by Valley	Non-lead - Other	ban Installation date after lead	Non-	-Lead		
	PUYALLUP, WA, 98372- 15211 87 ST E,			ban Installation date after lead	map (C-5) Service line material is poly		ban Installation date after lead				
001273	PUYALLUP, WA, 98372-	Non-lead - Other	No	ban	Information provided by Valley map (C-5) Service line material is poly	Non-lead - Other	ban	Non-	-Lead		
001274	15217 87 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (C-5) Service line material is poly	Non-lead - Other	Installation date after lead ban	Non-	-Lead		
001275	15218 86 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-	-Lead		
001276	15216 86 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-	-Lead		
001278	15204 86 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-	-Lead		

001279	15108 86 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001280	15104 86 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001281	15016 86 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001283	15103 86 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001285	15205 86 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001286	15209 86 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001287	15215 86 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001288	15219 86 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001289	15212 85 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001290	15208 85 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001291	15204 85 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001292	15202 85 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001293	15108 85 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001294	15102 85 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001295	15016 85 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001296	87 ST E & SR 162 E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Irrigation meter	Non-Lead		
001400	14927, 128 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001401	15101 85 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001402	15210 86 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001403	8612 150 AVE CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001404	8604 150 AVE CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001405	15115 87 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001406	15017 86 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		

001407	15107 86 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001408	15015 85 ST CT E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001409	SR 162 & 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Irrigation meter	Non-Lead		
001410	15021 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001411	15027 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001412	15103 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001413	15311 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001414	15319 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001415	15516 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001416	15325 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001417	15326 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001418	14721, PIONEER WAY E, PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.			
001419	15208 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001420	4112, PIONEER WAY E, PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.			
001421	15110 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001422	15414 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001423	15406 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001424	15104 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001425	15028 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001426	14053, PIONEER WAY E, PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		

						No Leaa nas ever been					
	14053, PIONEER WAY					detected or discovered in any					
001426-FSB	E, PUYALLUP, WA,	Fire Standby service at	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm	Non-lead - Other	Installation date after lead	Unknown		
001120102	98372-	this location	Cimiletin Cimileiy iedd	zon c mion	oune.	through maintenance, repairs	non read other	ban			
	98372-					through maintenance, repairs					
						Service line material is poly					
001427	15503 88 ST E,		Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-Lead		
001427	PUYALLUP, WA, 98372-		Non read States	740	ban	map (C-5)	Non lead other	ban	Non Ecad		
	15022 88 ST E,				Installation date after lead	Service line material is poly		Installation date after lead			
001428	PUYALLUP, WA, 98372-		Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	Non-Lead		
	101712201, 1171, 30372				Sun	map (C-5)		Suit			
						No Lead has ever been					
						detected or discovered in any					
						portion of the water sysetm					
001430	14721, 113 ST E,		Halmanna Halibah land	D = = 14 1 = = - · ·	Oth		Non-load Other	Installation date after lead	Halman		
001430	PUYALLUP, WA, 98374-		Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Non-lead - Other	ban	Unknown		
						or replacement since the					
						District took over operations of					
						this system.					
						No Lead has ever been					
						detected or discovered in any					
						portion of the water sysetm					
001431	14713, 113 ST E,		Unknown Unlikali land	Don't know	Other	through maintenance, repairs	Non-lead - Other	Installation date after lead	Unknown		
001431	PUYALLUP, WA, 98374-		Unknown - Unlikely lead	Don t know	Other		Non-leda - Other	ban	Olikilowii		
						or replacement since the					
						District took over operations of					
						this system.					
	45046 00 ST 5					Service line material is poly					
001432	15016 88 ST E,		Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-Lead		
	PUYALLUP, WA, 98372-				ban	map (C-5)		ban			
						Service line material is poly					
	15109 88 ST E,				Installation date after lead			Installation date after lead			
001433	PUYALLUP, WA, 98372-		Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	Non-Lead		
						map (C-5)					
	15504 88 ST 5				Installation data after load	Service line material is poly		Installation data after load			
001434	15504 88 ST E,		Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-Lead		
	PUYALLUP, WA, 98372-				ban	map (C-5)		ban			
						Service line material is poly					
001435	15515 88 ST E,		Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-Lead		
001433	PUYALLUP, WA, 98372-		Non-leda - Other	NO	ban		Non-leda - Other	ban	Non-Leau		
						map (C-5)					
	15509 88 ST E,				Installation date after lead	Service line material is poly		Installation date after lead			
001436	PUYALLUP, WA, 98372-		Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	Non-Lead		
	FUTALLUF, WA, 38372				buii	map (C-5)		Bull			
						Service line material is poly					
001437	15202 88 ST E,		Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-Lead		
001.07	PUYALLUP, WA, 98372-		Non read other		ban	map (C-5)	non read other	ban	Thom 2000		
	15510 88 ST E,				Installation date after lead	Service line material is poly		Installation date after lead			
001438	PUYALLUP, WA, 98372-		Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	Non-Lead		
						map (C-5)					
	15607.00 CT 5				Installation data after load	Service line material is poly		Installation data after load			
001439	15607 88 ST E,		Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-Lead		
	PUYALLUP, WA, 98372-				ban	map (C-5)		ban			
						Service line material is poly					
001440	15608 88 ST E,		Non load Other	Ma	Installation date after lead		Non load Other	Installation date after lead	Non-Load		
001440	PUYALLUP, WA, 98372-		Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	Non-Lead		
						map (C-5)					
	15207 88 ST E,				Installation date after lead	Service line material is poly		Installation date after lead			
001441	PUYALLUP, WA, 98372-		Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	Non-Lead		
	1 JIALLOI , WA, 30372-				buil	map (C-5)		Buil			
	45242 00 00 0					Service line material is poly					
001442	15212 88 ST E,		Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-Lead		
	PUYALLUP, WA, 98372-		23.6		ban	map (C-5)		ban			
	15123 88 ST E,				Installation date after lead	Service line material is poly		Installation date after lead			
001443	PUYALLUP, WA, 98372-		Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	Non-Lead		
					- 077	map (C-5)					
	15301 00 CT 5				Installation data after 1	Service line material is poly		Installation data often			
001444	15201 88 ST E,		Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-Lead		
	PUYALLUP, WA, 98372-				ban	map (C-5)		ban			
						Service line material is poly					
001445	15215 88 ST E,		Non-land Other	Ma	Installation date after lead		Non land Other	Installation date after lead	Nor Land		
001445	PUYALLUP, WA, 98372-		Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	Non-Lead		
						map (C-5)					
	15422 88 ST E,				Installation date after lead	Service line material is poly		Installation date after lead			
001446			Non-lead - Other	No		Information provided by Valley	Non-lead - Other		Non-Lead		
	PUYALLUP, WA, 98372-				ban	map (C-5)		ban			
						Service line material is poly					
001447	15005 88 ST E,		Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-Lead		
001447	PUYALLUP, WA, 98372-		Hon read Other	,,,	ban		Hon ledd Other	ban	Non Ecad		
						map (C-5)					

001448	15405 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001449	15601 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001450	15421 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001451	15124 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001452	15008 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001453	15303 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001454	15118 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001455	15117 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001456	15211 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001457	14803, 94 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001458	88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Park Irrigation Meter	Non-Lead		
001459	9202, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001460	15511, 96 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001461	14903, 94 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001462	14905, 94 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001463	14907, 94 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		

001464	14909, 94 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001465	15015 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001466	15009 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001467	15413 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5) Service line material is poly	Non-lead - Other	Installation date after lead ban	Non-Lead		
001468	15304 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (C-5) Service line material is poly	Non-lead - Other	Installation date after lead ban	Non-Lead		
001469	15216 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (C-5) No Lead has ever been	Non-lead - Other	Installation date after lead ban	Non-Lead		
001470	14811, 94 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001471	14815, 94 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001472	14807, 94 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001473	15523 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001474	15524 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001475	15320 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5) Service line material is poly	Non-lead - Other	Installation date after lead ban	Non-Lead Non-Lead		
001476	15312 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (C-5) No Lead has ever been	Non-lead - Other	Installation date after lead ban	Non-Lead		
001477	102 ST E AND 151 AVE CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001478	14923, 94 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		

001479	14925, 94 ST CT E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of	Non-lead - Other	Installation date after lead ban		Unknown		
001481	15503, 114 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations	Unknown		
001482	11009, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	of this system. No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001483	14220, PIONEER WAY E, PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001484	11107, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001485	12903, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001486	14801, 128 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001487	14804, 115 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001488	9415, SR 162 E, PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001490	15012 88 ST E, PUYALLUP, WA, 98372-	Non-lead - Other	No	Installation date after lead ban	Service line material is poly Information provided by Valley map (C-5)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001491	80 ST E, PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		

001492	7905, 143 AVE CT E, PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001493	14707, 80TH ST E, PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001494	15309, 106 ST E, PUYALLUP, WA, 98374-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001495	15003, 90 ST E, PUYALLUP, WA, 98372-		Non-lead - Other	No	Installation date after lead ban	Service line material is Poly Information provided by Valley map (A-4)	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001496	15002, 90 ST E, PUYALLUP, WA, 98372-		Non-lead - Other	No	Installation date after lead ban	Service line material is Poly Information provided by Valley map (A-4)	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001497	14107, PIONEER WAY E, PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001497-FSB	14107, PIONEER WAY E, PUYALLUP, WA, 98372-	Fire Standby service at this location	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001498	14119, PIONEER WAY E, PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001498-FSB	14119, PIONEER WAY E, PUYALLUP, WA, 98372-	Fire Standby service at this location	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001499	15011, 90 ST E, PUYALLUP, WA, 98372-		Non-lead - Other	No	Installation date after lead ban	Service line material is Poly Information provided by Valley map (A-4)	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		

001500	128 ST E AND SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlik	ely lead Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001501	15010, 90 ST E, PUYALLUP, WA, 98372-	Non-lead - Oi	her No	Installation date after lead ban	Service line material is Poly Information provided by Valley map (A-4)	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001502	15107, 90 ST E, PUYALLUP, WA, 98372-	Non-lead - O	her No	Installation date after lead ban	Service line material is Poly Information provided by Valley map (A-4)	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001503	15112, 90 ST E, PUYALLUP, WA, 98372-	Non-lead - O	her No	Installation date after lead ban	Service line material is Poly Information provided by Valley map (A-4)	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001504	15113, 90 ST E, PUYALLUP, WA, 98372-	Non-lead - Oi	her No	Installation date after lead ban	Service line material is Poly Information provided by Valley map (A-4)	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001505	15106, 90 ST E, PUYALLUP, WA, 98372-	Non-lead - Oi	her No	Installation date after lead ban	Service line material is Poly Information provided by Valley map (A-4)	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001506	8010, SR 162 E, PUYALLUP, WA, 98372-	Unknown - Unlik	ely lead Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001507	14224, PIONEER WAY E, PUYALLUP, WA, 98372-	Unknown - Unlik	ely lead Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001508	12403, SR 162 E (MTR 2 OF 2), PUYALLUP, WA, 98374-	Unknown - Unlik	ely lead Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001509	14306, 128 ST E, PUYALLUP, WA, 98374-	Unknown - Unlik	ely lead Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		

					No Lead has ever been			No Lead has ever been			
					detected or discovered in any portion of the water sysetm			detected or discovered in any portion of the water sysetm			
001510	14308, 128 ST E,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Unknown - Unlikely lead	Other	through maintenance, repairs	Unknown		
	PUYALLUP, WA, 98374-	, and the second se			or replacement since the			or replacement since the			
					District took over operations of			District took over operations			
					this system. No Lead has ever been			of this system.			
					detected or discovered in any						
	13505, PIONEER WAY				portion of the water sysetm		Installation date after lead				
001511	E, PUYALLUP, WA,	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Non-lead - Other	ban		Unknown		
	98372-				or replacement since the District took over operations of						
					this system.						
					No Lead has ever been						
	42505 01041550 14/41/				detected or discovered in any						
001512	13505, PIONEER WAY E, PUYALLUP, WA,	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs	Non-lead - Other	Installation date after lead		Unknown		
	98372-				or replacement since the		ban				
					District took over operations of						
					this system. Service Line Material is Poly						
001513	1308, 34 ST SE,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
	PUYALLUP, WA, 98372			ban	map (B-6)		ban				
001514	1307, 34 ST SE,	Non-lead - Other	No	Installation date after lead	Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
001314	PUYALLUP, WA, 98372	Non-lead - Other	NO	ban	map (B-6)	Non-ieda - Other	ban		Non-Leau		
	1305, 34 ST SE,			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001515	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban		Non-Lead		
	3307, HIGHLANDS				map (B-6) Service Line Material is Poly						
001516	BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
	98372			ban	map (B-6)		ban				
001517	1212, ST ANDREWS CT, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
001317	98372	Non-lead - Other	NO	ban	map (B-6)	Non-ledu - Other	ban		Non-Leau		
	1218, ST ANDREWS			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001518	CT, PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban		Non-Lead		
					map (B-6) Service Line Material is Poly						
001519	1306, 34 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley	Non-lead - Other	Installation date after lead ban		Non-Lead		
	101/12201, 11/1, 30372			bun	map (B-6)		Dun				
001520	1309, 34 ST SE,	Non-lead - Other	No	Installation date after lead	Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
	PUYALLUP, WA, 98372			ban	map (B-6)		ban				
					No Lead has ever been						
					detected or discovered in any portion of the water sysetm						
001521	15007, 116 ST E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	through maintenance, repairs	Non-lead - Other	Installation date after lead ban		Unknown		
	PUTALLUP, WA, 98374-				or replacement since the		Duri				
					District took over operations of this system.						
	1213, ST ANDREWS			Installation data after land	Service Line Material is Poly		Installation data often land				
001522	CT, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley	Non-lead - Other	Installation date after lead ban		Non-Lead		
	98372 3909, HIGHLANDS				map (B-6) Service Line Material is Poly						
001523	BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
	98372			ban	map (B-6)		ban				
001534	3911, HIGHLANDS	Non-land Other	No	Installation date after lead	Service Line Material is Poly	Non load Other	Installation date after lead		Non Load		
001524	BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley map (B-6)	Non-lead - Other	ban		Non-Lead		
	4008, HIGHLANDS			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001525	BLVD, PUYALLUP, WA,	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban		Non-Lead		
	98372 4010, HIGHLANDS				map (B-6) Service Line Material is Poly						
001526	BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
	98372			ban	map (B-6)		ban				
001527	1301, 34 ST SE,	Non-lead - Other	No	Installation date after lead	Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
001327	PUYALLUP, WA, 98372	Non-leau - Other	INU	ban	map (B-6)	Non-leuu - Other	ban		INOII-LEau		
	1320, 34 ST SE,			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001528	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban		Non-Lead		
					map (B-6)						

001529	1404, 34 ST SE,			In the Heating state of the classed	Service Line Material is Poly						
	PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley	Non-lead - Other	Installation date after lead ban		Non-Lead		
				Duri	map (B-6)		buri				
	4006, HIGHLANDS			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001530	BLVD, PUYALLUP, WA,	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban		Non-Lead		
	98372				map (B-6) Service Line Material is Poly						
001531	1419, 34 ST SE,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
001331	PUYALLUP, WA, 98372	Non lead outer	,,,,	ban	map (B-6)	wow read coner	ban		11011 2000		
	4402 24 57 55				Service Line Material is Poly						
001532	1402, 34 ST SE,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead ban		Non-Lead		
	PUYALLUP, WA, 98372			ban	map (B-6)		bull				
	1322, 34 ST SE,			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001533	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban		Non-Lead		
	3510, HIGHLANDS				map (B-6)						
001534	BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
001334	98372	Non read Street	710	ban	map (B-6)	Woll lead Other	ban		Non Ecua		
	4015, HIGHLANDS			lantallation data after land	Service Line Material is Poly		Installation data often land				
001535	BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley	Non-lead - Other	Installation date after lead ban		Non-Lead		
	98372			buil	map (B-6)		Bull				
	4022, HIGHLANDS			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001536	BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban		Non-Lead		
	4024, HIGHLANDS				map (B-6) Service Line Material is Poly						
001537	BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
	98372			ban	map (B-6)		ban				
	4026, HIGHLANDS			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001538	BLVD, PUYALLUP, WA,	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban		Non-Lead		
	98372				map (B-6)						
001539	4004, HIGHLANDS BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
001559	98372	Non-lead - Other	NO	ban	map (B-6)	Non-leuu - Other	ban		Non-Leau		
					Service Line Material is Poly						
001540	1303, 34 ST SE,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
	PUYALLUP, WA, 98372			ban	map (B-6)		ban				
	1318, 34 ST SE,			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001541	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban		Non-Lead		
					map (B-6) Service Line Material is Poly						
001542	1406, 34 ST SE,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
	PUYALLUP, WA, 98372			ban	map (B-6)		ban				
	1311, 34 ST SE,			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001543	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban		Non-Lead		
				2011	map (B-6)		54.1				
001544	3516, HIGHLANDS	Non-land Other	No	Installation date after lead	Service Line Material is Poly	Non load Other	Installation date after lead	leria ation mater	Non Lood		
001544	BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley map (B-6)	Non-lead - Other	ban	Irrigation meter	Non-Lead		
	3917, HIGHLANDS				Service Line Material is Poly						
001545	BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
	98372			ban	map (B-6)		ban				
	4027, HIGHLANDS			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001546	BLVD, PUYALLUP, WA,	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban		Non-Lead		
	98372 4025, HIGHLANDS				map (B-6) Service Line Material is Poly						
001547	BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
	98372	11		ban	map (B-6)		ban				
	4023, HIGHLANDS			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001548	BLVDPUYALLUP, WA,	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban		Non-Lead		
	98372			Zun	map (B-6)		5011				
001540	4021, HIGHLANDS	Non-load Other	No	Installation date after lead	Service Line Material is Poly	Non load Other	Installation date after lead		Non Load		
001549	BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley map (B-6)	Non-lead - Other	ban		Non-Lead		
	4019, HIGHLANDS				Service Line Material is Poly						
001550	BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
	98372			ban	map (B-6)		ban				
	4017, HIGHLANDS			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001551	BLVD, PUYALLUP, WA,	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban		Non-Lead		
	98372 4013, HIGHLANDS				map (B-6) Service Line Material is Poly						
001552	BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
001332	98372			ban	map (B-6)		ban				

					Service Line Material is Poly						
001553	1133, 35 ST PL SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001554	1129, 35 ST PL SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001555	4014, HIGHLANDS BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001556	4016, HIGHLANDS BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001557	4018, HIGHLANDS BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001558	4020, HIGHLANDS BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001559	3921, HIGHLANDS BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001560	1212, 35 ST PL SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001561	1120, 35 ST PL SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001562	1125, 35 ST PL SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001563	1126, 35 ST PL SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001564	1205, 35 ST PL SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001565	1206, 35 ST PL SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001566	3927, HIGHLANDS BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001567	3919, HIGHLANDS BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001568	4012, HIGHLANDS BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001569	11822, SR 162 E, PUYALLUP, WA, 98374-	Non-lead - Other	Don't know	Service line repair/replacement record	Repair/Replacement done 01/02/2014	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.			
001570	11810, SR 162 E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.			
001571	1302, 34 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	, ,	Non-Lead		
001572	4007, HIGHLANDS BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001573	3912, HIGHLANDS BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001574	3914, HIGHLANDS BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		

001575	3923, HIGHLANDS BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001576	14308, MILITARY RD E, PUYALLUP, WA, 98374-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001577	1409, 34 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	G, time systems	Non-Lead		
001578	1405, 34 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001579	1211, 35 ST PL SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001580	1132, 35 ST PL SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001581	1304, 34 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001582	3309, HIGHLANDS BLVD, PUYALLUP WA, 98372 4005, HIGHLANDS	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6) Service Line Meterial is Poly	Non-lead - Other	Installation date after lead ban		Non-Lead		
001583	4005, HIGHLANDS BLVD, PUYALLUP, WA, 98372 3920, HIGHLANDS	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban		Non-Lead		
001584	BLVD, PUYALLUP, WA, 98372 3922, HIGHLANDS	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban		Non-Lead		
001585	BLVD, PUYALLUP, WA, 98372 3924, HIGHLANDS	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban		Non-Lead		
001586	BLVD, PUYALLUP, WA, 98372 3930, HIGHLANDS	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban		Non-Lead		
001587	BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban		Non-Lead		
001588	1417, 34 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001589	3504, HIGHLANDS BLVD, PUYALLUP, WA, 98372 4009, HIGHLANDS	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001590	BLVD, PUYALLUP, WA, 98372 4011, HIGHLANDS	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban		Non-Lead		
001591	BLVD, PUYALLUP, WA, 98372 3906, HIGHLANDS	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban		Non-Lead		
001592	BLVD, PUYALLUP, WA, 98372 3910, HIGHLANDS	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban		Non-Lead		
001593	BLVD, PUYALLUP, WA, 98372 4002, HIGHLANDS	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001594	4002, HIGHLANDS BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban		Non-Lead		
001595	1313, 34 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban		Non-Lead		
001596	1315, 34 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban		Non-Lead		
001597	1407, 34 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		

001598	1415, 34 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001599	1418, 34 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001600	3931, HIGHLANDS BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001601	3908, HIGHLANDS BLV, DPUYALLUP, WA,	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead ban		Non-Lead		
001602	98372 3926, HIGHLANDS BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead ban	map (B-6) Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
001603	98372 1304, 37 ST PL SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	map (B-6) Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
001604	1308, 37 ST PL SE,	Non-lead - Other	No	Installation date after lead	map (B-6) Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
001605	1312, 37 ST PL SE,	Non-lead - Other	No	Installation date after lead	map (B-6) Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
001606	1316, 37 ST PL SE,	Non-lead - Other	No	ban Installation date after lead	map (B-6) Service Line Material is Poly Information provided by Valley	Non-lead - Other	ban Installation date after lead		Non-Lead		
001607	1320, 37 ST PL SE,	Non-lead - Other	No	ban Installation date after lead	map (B-6) Service Line Material is Poly Information provided by Valley	Non-lead - Other	ban Installation date after lead		Non-Lead		
	PUYALLUP, WA, 98372 1324, 37 ST PL SE,			ban Installation date after lead	map (B-6) Service Line Material is Poly		ban Installation date after lead				
001608	PUYALLUP, WA, 98372 3811, VICTORIA LANE	Non-lead - Other	No	ban Installation date after lead	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	ban Installation date after lead		Non-Lead		
001609	CT SE, PUYALLUP, WA, 98372 3925, HIGHLANDS	Non-lead - Other	No	ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	ban	Irrigation meter	Non-Lead		
001610	BLVD, PUYALLUP, WA, 98372 3934, HIGHLANDS	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban		Non-Lead		
001611	BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001612	1438, 39 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001613	1404, 39 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001614	1408, 39 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001615	1412, 39 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001616	1416, 39 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001617	3933, HIGHLANDS BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001618	3901, HIGHLANDS BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001619	3904, HIGHLANDS BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead ban		Non-Lead		
	98372				map (B-6) No Lead has ever been detected or discovered in any						
001620	14224, PIONEER WAY E, PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	portion of the water sysetm through maintenance, repairs or replacement since the	Non-lead - Other	Installation date after lead ban		Unknown		
					District took over operations of this system.						

001620-FSB	14224, PIONEER WAY E, PUYALLUP, WA, 98372-	Fire Standby service at this location	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Unknown		
001621	3929, HIGHLANDS BLVD, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001622	3913, HIGHLANDS BLVD, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001623	1408, 34 ST SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001624	1335, 37 ST PL SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	Non-Lead Non-Lead		
001625	1331, 37 ST PL SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	Non-Lead Non-Lead		
001626	1327, 37 ST PL SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	Non-Lead		
001627	1323, 37 ST PL SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban	Non-Lead Non-Lead		
001628	1319, 37 ST PL SE, PUYALLUP, WA, 98372 3701, HIGHLANDS		Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban	Non-Lead Non-Lead		
001629	BLVD, PUYALLUP, WA, 98372 3609, HIGHLANDS		Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban	Non-Lead Non-Lead		
001630	BLVD, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban	Non-Lead		
001631	1328, 37 ST PL SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban	Non-Lead		
001632	1332, 37 ST PL SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban	Non-Lead		
001633	1336, 37 ST PL SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban	Non-Lead		
001634	1340, 37 ST PL SE, PUYALLUP, WA, 98372		Non-lead - Other	No		Service Line Material is Poly Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead	Non-Lead		
001635	1316, 34 ST SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban	Non-Lead		
001636	1411, 34 ST SE, PUYALLUP, WA, 98372 1321, 34 ST SE,		Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban Installation date after lead	Non-Lead		
001637	1321, 34 51 5E, PUYALLUP, WA, 98372 3932, HIGHLANDS		Non-lead - Other	No	Installation date after lead ban Installation date after lead	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	ban Installation date after lead	Non-Lead		
001638	BLVD, PUYALLUP, WA, 98372 3515, HIGHLANDS		Non-lead - Other	No	ban Installation date after lead	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	ban	Non-Lead		
001639	98372 1315, 37 ST PL SE,		Non-lead - Other	No	ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban Installation date after lead	Non-Lead		
001640	PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban Installation date after lead	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban Installation date after lead	Non-Lead		
001641	1311, 37 ST PL SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	Installation date after lead ban	Non-Lead		
001642	1307, 37 ST PL SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	Non-Lead		

001643	1410, 34 ST SE,	Non-lead - Other	No	Installation date after lead	Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead	No	on-Lead		
	PUYALLUP, WA, 98372			ban	тар (В-6)		ban				
	3401, HIGHLANDS			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001644	BLVD, PUYALLUP, WA,	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	No	on-Lead		
	98372				map (B-6)						
001645	1317, 34 ST SE,	Non-land Other	A1-	Installation date after lead	Service Line Material is Poly	Non-land Other	Installation date after lead	l l			
001645	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley map (B-6)	Non-lead - Other	ban	INC.	on-Lead		
	3928, HIGHLANDS				Service Line Material is Poly						
001646	BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	No.	on-Lead		
002070	98372	Non read States	,	ban	map (B-6)	Trom redu Garier	ban		on 2000		
					Service Line Material is Poly						
001647	1319, 34 ST SE,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	No	on-Lead		
	PUYALLUP, WA, 98372			ban	тар (В-6)		ban				
	1314, 34 ST SE,			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001648	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	No	on-Lead		
	, ,				map (B-6)						
001649	1303, 37 ST PL SE,	Non-lead - Other	No	Installation date after lead	Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead	Ne	on-Lead		
001049	PUYALLUP, WA, 98372	Non-leda - Other	NO	ban	map (B-6)	Non-leda - Other	ban	l like	on-Leau		
					Service Line Material is Poly						
001650	3816, VICTORIA LN CT,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	No	on-Lead		
	PUYALLUP, WA, 98372			ban	map (B-6)		ban				
	3822, VICTORIA LN CT,			Installation date after lead	Service Line Material is Poly		Installation data after land				
001651	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	Installation date after lead ban	No	on-Lead		
	1 01ALLO1, WA, 30372			bull	map (B-6)		bun				
	3902, VICTORIA LN,			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001652	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	No	on-Lead		
					map (B-6) Service Line Material is Poly						
001653	3916, VICTORIA LN,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	No.	on-Lead		
001033	PUYALLUP, WA, 98372	Non lead other	710	ban	map (B-6)	Non lead Other	ban		on Leau		
					Service Line Material is Poly						
001654	1402, 40 ST SE,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	No	on-Lead		
	PUYALLUP, WA, 98372			ban	map (B-6)		ban				
	3908, 14 AVE SE,			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001655	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	No	on-Lead		
					map (B-6)						
001656	3935, HIGHLANDS BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead	No	on-Lead		
001030	98372	Non-ieuu - Other	140	ban	map (B-6)	Non-ledu - Other	ban	l like	on-Leau		
					Service Line Material is Poly						
001657	1424, 39 ST SE,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	No	on-Lead		
	PUYALLUP, WA, 98372			ban	map (B-6)		ban				
	1428, 39 ST SE,			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001658	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	No	on-Lead		
	7 0 77 12201 7 177 7 3037 2			2011	map (B-6)						
001650	3924, VICTORIA LN,	New Jeans Other	A1-	Installation date after lead	Service Line Material is Poly	Non-land Other	Installation date after lead	l No			
001659	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley map (B-6)	Non-lead - Other	ban	IN S	on-Lead		
	4003, HIGHLANDS				Service Line Material is Poly						
001660	BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	No	on-Lead		
	98372			ban	map (B-6)		ban				
	3905, HIGHLANDS			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001661	BLVD, PUYALLUP, WA,	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	No	on-Lead		
	98372			Vari	map (B-6)		Juli				
004655	1420, 39 ST SE,		• •	Installation date after lead	Service Line Material is Poly	Man I I all	Installation date after lead				
001662	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley map (B-6)	Non-lead - Other	ban	No	on-Lead		
	3907, HIGHLANDS				Service Line Material is Poly						
001663	BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	No	on-Lead		
112300	98372	113.77644 50.16.		ban	map (B-6)		ban				
	3813, HIGHLANDS			Installation date after lead	Service Line Material is Poly		Installation data after land				
001664	BLVD, PUYALLUP, WA,	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	Installation date after lead ban	No	on-Lead		
	98372			Duli	map (B-6)		buil				
	3711, HIGHLANDS			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001665	BLVD, PUYALLUP, WA,	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	No	on-Lead		
	98372 3915, HIGHLANDS				map (B-6) Service Line Material is Poly						
001666	BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	No	on-Lead		
132000	98372		•	ban	map (B-6)		ban				
										•	

	2707 1116111 ANDS				Coming time Adaptamint in Date						
001667	3707, HIGHLANDS BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead	Non-L	Lead		
001007	98372	Non-lead - Other	NO	ban	map (B-6)	Non-leda - Other	ban	INOTI-L	Leau		
	36372				Service Line Material is Poly						
001668	3910, VICTORIA LN,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-L	Lead		
	PUYALLUP, WA, 98372			ban	map (B-6)		ban				
					Service Line Material is Poly						
001669	1418, 40 ST SE,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-L	Lead		
	PUYALLUP, WA, 98372			ban	map (B-6)		ban				
	1434 40 ST ST				Service Line Material is Poly						
001670	1424, 40 ST SE,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-L	Lead		
	PUYALLUP, WA, 98372			ban	map (B-6)		ban				
	4001, HIGHLANDS			Installation data after load	Service Line Material is Poly		Installation data after load				
001671	BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley	Non-lead - Other	Installation date after lead ban	Non-L	Lead		
	98372			buii	map (B-6)		Bull				
	3903, HIGHLANDS			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001672	BLVD, PUYALLUP, WA,	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	Non-L	Lead		
	98372				map (B-6)						
	3815, HIGHLANDS			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001673	BLVD, PUYALLUP, WA,	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	Non-L	Lead		
	98372				map (B-6)						
001674	1310, 34 ST SE,	Non-lead - Other	No	Installation date after lead	Service Line Material is Poly	Non load Other	Installation date after lead	Non I	Load		
001674	PUYALLUP, WA, 98372	Non-ieuu - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	Non-L	Leau		
					map (B-6) Service Line Material is Poly						
001675	1423, 34 ST SE,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-L	heal		
001073	PUYALLUP, WA, 98372	Non ledd Other	740	ban	map (B-6)	Non ledd Other	ban	Non E	Leau		
					Service Line Material is Poly						
001676	1445, 40 ST SE,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-L	Lead		
	PUYALLUP, WA, 98372			ban	map (B-6)		ban				
	4444 40 ST ST				Service Line Material is Poly						
001677	1441, 40 ST SE,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-L	Lead		
	PUYALLUP, WA, 98372			ban	map (B-6)		ban				
	1410, 40 ST SE,			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001678	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	Non-L	Lead		
	FUTALLUF, WA, 38372			buii	тар (В-6)		Bun				
	1430, 40 ST SE,			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001679	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	Non-L	Lead		
	, , , , , , , , , , , , , , , , , , , ,				map (B-6)						
001600	1438, 40 ST SE,	Non-land Other	A/-	Installation date after lead	Service Line Material is Poly	Non-land Other	Installation date after lead	No.	Land		
001680	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley map (B-6)	Non-lead - Other	ban	Non-L	Leau		
					Service Line Material is Poly						
001681	1413, 34 ST SE,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-L	Lead		
001001	PUYALLUP, WA, 98372	Non lead States	710	ban	map (B-6)	Non lead Other	ban	Non E	Lead		
					Service Line Material is Poly						
001682	1403, 34 ST SE,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-L	Lead		
	PUYALLUP, WA, 98372			ban	map (B-6)		ban				
	3311, HIGHLANDS			Installation data after load	Service Line Material is Poly		Installation data after load				
001683	BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley	Non-lead - Other	Installation date after lead ban	Non-L	Lead		
	98372			buii	тар (В-6)		Bun				
	3909, VICTORIA LN,			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001684	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	Non-L	Lead		
	, , , , , , , , , , , , , , , , , , , ,				map (B-6)						
204625	1312, 34 ST SE,		**	Installation date after lead	Service Line Material is Poly	Man I I all	Installation date after lead		1 1		
001685	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	Non-L	Lead		
	3305, HIGHLANDS				map (B-6) Service Line Material is Poly						
001686	BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-L	heal		
001000	98372	Non-leau - Other	740	ban	map (B-6)	THOM TOUR TOURE	ban	14011-1	Lead		
	4029, HIGHLANDS				Service Line Material is Poly						
001687	BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead	Information provided by Valley	Non-lead - Other	Installation date after lead	Non-L	Lead		
	98372			ban	map (B-6)		ban				
				Installation date after lead	Service Line Material is Poly		Installation data after I				
001688	3809, VICTORIA LN CT, PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	Installation date after lead ban	Non-L	Lead		
	101ALLOF, WA, 98372			Dull	map (B-6)		Dun				
	3803, VICTORIA LN CT,			Installation date after lead	Service Line Material is Poly		Installation date after lead				
001689	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley	Non-lead - Other	ban	Non-L	Lead		
	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				map (B-6)						
001600	3804, VICTORIA LN CT,	Non-land Other	Ma	Installation date after lead	Service Line Material is Poly	Non land Other	Installation date after lead		Load		
001690	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley map (B-6)	Non-lead - Other	ban	Non-L	Leau		
					IIIup (D-U)						

001691	3810, VICTORIA LN CT, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead	Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead		Non-Lead		
001692	13707, PIONEER WAY E, PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	map (B-6) No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001692-FSB	13707, PIONEER WAY E, PUYALLUP, WA, 98372-	Fire Standby service at this location	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban		Unknown		
001693	13707, PIONEER WAY E, PUYALLUP, WA, 98372-		Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Non-lead - Other	Installation date after lead ban	Irrigation meter	Unknown		
001694	1414, 34 ST SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001695	1437, 40 ST SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001696	1433, 40 ST SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001697	1425, 40 ST SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001698	1421, 40 ST SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001699	1429, 40 ST SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001700	1421, 34 ST SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001701	1425, 39 ST SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001702	1217, ST ANDREWS CT, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly	Non-lead - Other	Installation date after lead ban		Non-Lead		
001703	1412, 34 ST SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001704	1416, 34 ST SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001705	3511, HIGHLANDS BLVD, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001706	1431, 39 ST SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001707	1415, 39 ST SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001708	15015, 106 ST E, PUYALLUP, WA, 98374-		Non-lead - Other	No	Installation record	Service line material is Poly Installation done 11/13/2014	Non-lead - Other	Installation date after lead ban		Non-Lead		
001709	1420, 34 ST SE, PUYALLUP, WA, 98372		Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		

					Service Line Material is Poly						
001710	1437, 39 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	Nor	n-Lead		
001711	1421, 39 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	Nor	n-Lead		
001712	3917, VICTORIA LN, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead ban	Nor	n-Lead		
001713	3605, HIGHLANDS BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead ban	map (B-6) Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead ban	Nor	n-Lead		
001714	98372 10906, SR 162 E,	Non-lead - Other	No	Installation record	map (B-6) Service line material is Poly	Non-lead - Other	Installation date after lead	Nor	n-Lead		
001715	1320, 39 ST SE,	Non-lead - Other	No	Installation date after lead	Installation done 6/9/2015 Service Line Material is Poly Information provided by Valley	Non-lead - Other	ban Installation date after lead	Nor	on-Lead		
	PUYALLUP, WA, 98372 1417, 40 ST SE,			ban Installation date after lead	map (B-6) Service Line Material is Poly		ban Installation date after lead				
001716	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	ban	Nor	n-Lead		
001717	3902, 14 AVE SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	Nor	n-Lead		
001718	1422, 34 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	Nor	n-Lead		
001719	15022, 106 ST E, PUYALLUP, WA, 98374-	Non-lead - Other	No	Installation record	Service line material is Poly Installation done 12/03/2015	Non-lead - Other	Installation date after lead ban	Nor	on-Lead		
001720	1432, 39 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	Nor	n-Lead		
001721	3304, HIGHLANDS BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	Nor	n-Lead		
001722	3308, HIGHLANDS BLVD, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	Nor	n-Lead		
001723	3901, 14 AVE SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	Nor	n-Lead		
001724	1413, 40 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead	Nor	on-Lead		
001725	3306, HIGHLANDS BLVD, PUYALLUP, WA,	Non-lead - Other	No	Installation date after lead ban	map (B-6) Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead ban	Nor	n-Lead		
001726	98372 1401, 40 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	information provided by valley	Non-lead - Other	Installation date after lead ban	Nor	on-Lead		
001727	1409, 40 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	map (B-6) Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead ban	Nor	n-Lead		
001728	1302, 39 ST SE,	Non-lead - Other	No	Installation date after lead	map (B-6) Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead	Nor	on-Lead		
001729	1314, 39 ST SE,	Non-lead - Other	No	ban Installation date after lead	map (B-6) Service Line Material is Poly Information provided by Valley	Non-lead - Other	Installation date after lead	Nor	on-Lead		
001730	1308, 39 ST SE,	Non-lead - Other		ban Installation date after lead	map (B-6) Service Line Material is Poly Information provided by Valley	Non-lead - Other	ban Installation date after lead		n-Lead		
	9913, 14 AVE SE,	ixun-leaa - Other	No	ban Installation date after lead	map (B-6) Service Line Material is Poly	Non-leau - Other	ban Installation date after lead	Nor	ni-Ledu		
001731	PUYALLUP, WA, 98372	Non-lead - Other	No	ban	Information provided by Valley map (B-6) Service Line Material is Poly	Non-lead - Other	ban	Nor	n-Lead		
001732	3919, 14 AVE SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	Nor	n-Lead		
001733	1405, 40 ST SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	Nor	on-Lead		

001734	3907, 14 AVE SE, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban		Non-Lead		
001735	10806, 159TH AVE E, PUYALLUP, WA, 98374-	Non-lead - Other	No	Installation record	Service line material is Poly Installation done 02/01/2018	Non-lead - Other	Installation date after lead ban		Non-Lead		
001736	3802, PIONEER WAY E, PUYALLUP, WA, 98372-	Unknown - Unlikely lead	Don't know	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown - Unlikely lead	Other	No Lead has ever been detected or discovered in any portion of the water sysetm through maintenance, repairs or replacement since the District took over operations of this system.	Unknown		
001737	3311, 8TH AVE SE (RESIDENCE), PUYALLUP, WA, 98372-	Non-lead Poly	No	Installation record - Step by Step DE	Step by Step DE plans	Non-lead - Poly	Installation record - Step by Step DE	Step by Step DE plans	Non-Lead		
001738	3303, 8TH AVE SE #A (OFFICE), PUYALLUP, WA, 98372-	Non-lead Poly	No	Installation record - Step by Step DE	Step by Step DE plans	Non-lead - Poly	Installation record - Step by Step DE	Step by Step DE plans	Non-Lead		
001739	3303, 8TH AVE SE #B (COMMONS), PUYALLUP, WA, 98372-	Non-lead Poly	No	Installation record - Step by Step DE	Step by Step DE plans	Non-lead - Poly	Installation record - Step by Step DE	Step by Step DE plans	Non-Lead		
001739-FSB	3303, 8TH AVE SE #B (COMMONS), PUYALLUP, WA, 98372-	Non-lead Poly	No	Installation record - Step by Step DE	Step by Step DE plans	Non-lead - Poly	Installation record - Step by Step DE	Step by Step DE plans	Non-Lead		
001740	3303, 8TH AVE SE #C (GATEWAY), PUYALLUP, WA, 98372-	Non-lead Poly	No	Installation record - Step by Step DE	Step by Step DE plans	Non-lead - Poly	Installation record - Step by Step DE	Step by Step DE plans	Non-Lead		
001741	3303, 8TH AVE SE #G (GH), PUYALLUP, WA, 98372-	Non-lead Poly	No	Installation record - Step by Step DE	Step by Step DE plans	Non-lead - Poly	Installation record - Step by Step DE	Step by Step DE plans	Non-Lead		
001742	14011, 80TH ST E, PUYALLUP, WA, 98372-	Non-lead Poly	No	Installation record	Installation done on 12/11/2019	Non-Lead -Other	Installation date after lead ban		Non-Lead		
001743	7913, 141ST AVE E, PUYALLUP, WA, 98372-	Non-lead Poly	No	Installation record	Installation done on 06/10/2020	Non-lead - Other	Installation date after lead ban		Non-Lead		
001744	1200, ST ANDREWS CT, PUYALLUP, WA, 98372	Non-lead - Other	No	Installation date after lead ban	Service Line Material is Poly Information provided by Valley map (B-6)	Non-lead - Other	Installation date after lead ban	VWD Irrigation meter	Non-Lead		
001745	14714, 115 ST CT E, PUYALLUP, WA, 98374-	Non-Lead Other	No	Installation record	Service line material is Poly Installation done 9/23/2021	Non-lead - Other	Installation date after lead ban		Non-Lead		
001746	12623, SR 162 E, PUYALLUP, WA, 98374-	Non-lead - Other	No	Installation record	Service line material is Poly Installation done 10/27/2021	Non-lead - Other	Installation date after lead ban		Non-Lead		
001748	15201-03, BOWMAN HILTON RD E, PUYALLUP, WA, 98372-	Non-lead Poly	No	Installation record	Installation done on 2/1/22	Non-lead Other	Installation date after lead ban		Non-Lead		
001749	11431, 154 AVE E, PUYALLUP, WA, 98374-	Non-lead - Other	No	Installation record	Service line material is Poly Installation done 03/16/2022	Non-lead - Other	Installation date after lead ban		Non-Lead		
001750	12627, SR 162 E, PUYALLUP, WA, 98374-	Non-lead - Other	No	Installation record - DE	Service line material is Poly Installation done as part of SR 162 Mini Storage DE	Non-lead - Other	Installation date after lead ban		Non-Lead		
001750-FSB	12627, SR 162 E, PUYALLUP, WA, 98374-	Non-lead - Other	No	Installation record - DE	Service line material is Poly Installation done as part of SR 162 Mini Storage DE	Non-lead - Other	Installation date after lead ban		Non-Lead		